## **LAND CORNER RECORDATION CERTIFICATE**Filing Requirement of Act 74, Mich. PA 1970

		quirement of Act 74,	
For Corners In: Kalkaska (County)	Located In	Corner Code #	
1. Public Land Survey	T <u>26N</u> R <u>6W</u> T R	V <u>L9</u>	
Property Controlling in Section S			
3. Miscellaneous Property in Section			
4. Lot No: R	ecorded Plat:		Register of Deeds Stamp & File Number
5. Private Claims:		A B C D E F G H I J K L M	
I, <u>Craig W. McVean</u> , in a field survey on <u>Feb. 23</u> , 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		3 4 — 7 — 8 — 9 — 10 — 11 — 12 — 5 — 18 — 17 — 16 — 15 — 14 — 13 — 7	
			12 31 32 33 34 35 36
A. Description of original me	onument and accessories a	ind/or subsequent resto	
1) Cedar 12" S78°W 10 L. 2) Cedar 10" N58°E 37 L. - <b>1975</b> – LCRC #363-A and Rec. Sur. L. 1, p.880 – H. L. Fluharty –		- 1978 – Consumers Power Co. Drawing No. S-F 17406 – Sheet 8 – D. A. Ankrom – Fd. ½" re-rod and cap 6) 8" Birch S55°W 3.72'; 7) 6" Birch S42°E 10.42'; 8) 6" Birch N77°E 31.89' – 2000 – Farrier Surveying File No. 9400 & 31300 – E. D. Farrier & D. R. Farrier – Fd. Iron and cap #12026; 6) Fd. Nail 8" Birch S56°W 3.4'; 8) Fd. Nail 4" Birch N73°E 31.75'; 9) Fd. Nail 4" Maple N75°W 24.4'; 10) 5/8" iron & cap #18223 – N89°08'43"E 20.04'	
B. Description of corner evi	dence found and/or method	d applied in restoring or	r re-establishing corner:
survey in Sec. 24. Use Stp. Witnesses #1, 2, 2631.00' – CPC, 2650 'M9 – A9'. It is appare and faithful reestablish - Reference Pt. – N89°0	ed by Consumers and Farri 3, 4, 5, 7, 8, and 9 are gone .28' – HLF, 2630.86 – Farr ant that Ostling reestablishe ament of the position of the	ier. No GLO evidence. e. Measured grid bear- rier) to 'K9' and S89°28 d this corner by single original corner.  /8" iron and cap #1822	cap in swamp by C. E. Ostling apparently set for a 1972. Fd. Witness #6 – Dead but measured 3.75' to fd. nail in ring and distance of N89°26'49"W 2630.23' (2634.06' – GLO 3'00"E 2631.56' (2634.06' – GLO, 2631.80' – CPC) to proportion to GLO – ½" iron and cap accepted as a careful cap. It is apparent a blunder was made in the establishment of
C. Description of monumen	t for corner and accessorie	s established to perpet	tuate locating the position of the corner:
L9 – Drove stamped 4" DNR Alum. Cap on 1" x 4' long galv. iron pipe over fd. ½" CIR – Up 6"  Set Blue Carsonite Post 1' SE  N83°W 47.01' to set N & T in N. side 6" Maple  S36°E 24.97' to set N & T in E. side 6" Maple  N27°E 90.08' to set N & T in N. side 10" Cedar scribed 'XBT'  S10°W 41.41' to set ½" x 18" rebar  N89°05'E 20.23' to fd. 5/8" CIR #18223 – Reference Pt. (#10)  Ro.  39088			
Signed by:  Surveyor's Michigan Lice	M. Mc () ense No.: 39088	Dan Dan	