SURVEY & REMONUMENTATION

FEB 1 3 1998

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	•			
KALKASKA	Located In:	Corner Code #		
(County)		:		
1997 REMONUMENTATION	:		:	
1. Public Land Survey	T_26N R_8W	_ 1_12		
	TR			
	T R			
	T R			
2. Property Controlling	S T R	·		
•	S T R			
in Section				
3. Miscellaneous	S TR			
Property in Sec.	S R		Register of Deeds Stamp & File Nu	mber
		·		
7				
4. Lot No, Reco	rded Plat		— ABCDEFGHIJI	C L M
•	!		1	
5. Private Claims	<u> </u>		$\frac{1}{2}$ $\frac{1}{5}$ $\frac{1}{5}$ $\frac{1}{4}$ $\frac{1}{3}$ $\frac{1}{2}$ $\frac{1}{2}$	i
			3	
	•			
	•		4 - 7 - 8 - 9 - 10 - 11 -	12-
I, EUGENE FARRIER	in a field reinvoy on C	CTORER 30 19 97		
i, EURIENE PARNIER	mirements of P A 74 Michigs	n P.A. of 1970, the corner poin	6 -18 -17 -16 -15 -14	13
mentioned in lines 1 and 2 sh	ove were in conformance with	regulations and rules therefore	as 7	
required in the current manual or	f survey instructions of the Unite	ed States Department of the Interio	pr. 8 19 20 21 22 23	24
Bureau of Land Management of	or by a decree of a Court of L	aw and /or that the corner poin.	its	1
mentioned in lines 3, 4 and 5 a	above were in conformance with	n the rules of the Michigan Board o	of 9	l
Land Surveyors or by a Decre	ee of a Court of Law; establi	shed, re-established, monumente	od, 10 30 29 28 27 26	25-
recovered, found as expressed b				
	. 1 b		11	
NOTE: Not more than 2 corners	s, all in the same town; and range,	may be recorded	12 31 32 33 34 4 35	36
on this certificate.	i i		13	
	1.		13.	
	0.00			
	:			
A. Description of original m	onument and accessories and	d/or subsequent restoration:		
I-12: 1/4 Cor. Common to Se	ec. 34 & 35, T26N-R8W, Br	ardman_Township		
1852, GLO resurvey, set pos	st, 10" Hemlock N49E, 35, 1	O" Hemlock S54W, 11		
10-20-1981, Granger Eng. In	nc., surveγ, fd. 1/2" bar, w/a	ccessories, Lib 2, Pg. 680		
70 20 100 // 2.a.igor = i.g. x		• • •		
8. Description of corner evi	dence found and/or method a	pplied in restoring or reestablis	hing corner:	
I-12: 1/4 Cor. Common to Se	ec. 34 & 35, T26N-R8W, Bo	ardman Township		
Ed. 1/2" x 24" B.B. 1.5' Fas	t of C.L. Creighton Bd. & 21	South of C.L. Luce Rd. Pulled	& replaced with 5/8" x 18" rebar w/brass	cap No
GLO witnesses were fd. The	Kalkaska Co. Peer group apr	roved & accepted the above m	nonument as the best available evidence of	the
position of the original corner				
position of the angular service	· •			
	. !	•		
	i			
	.: ;			

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-12: 1/4 Cor. Common to Sec. 34 & 35, T26N-R8W, Boardman Township

Fd. 1/2" x 24" R.B. 1.5' East of C.L. Creighton Rd. & 21' South of C.L. Luce Rd. Pulled & replaced with 5/8" x 18" rebar w/brass cap Set nail & tag N35W 12" R. Pine, 73.00'
Set nail & tag N42E 32" Maple, 79.42'
Set nail & tag S60E 10" R. Pine, 47.65'
Set nail & tag S45W P. Pole, 47.17'

Ratified by Peer Group

D A 245 1000 Kalkaska County

Ratified by Peer Group P.A. 345 - 1990 Kalkaska County

E OF MICHIGAL EUGENE D. FARRIER PROFESSIONAL SURVEYOR No. 24594 POFESSION

Signed by C

Date Z-3-98



3004849 Page: 1 of 1 02/04/98 11:22A