

## FEB 1 8 1994

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

For	corners in	Filing Requir	ement of Act 74, Mich. P.A. 19	RVENVERY COMPLETE Unpurent
1 ()				RECEIVED
	KALKASKA County) 1993 REMONUMENTATION	Located In:	Corner Code ##	1993 DEC 22 PN 1: 32
1.	Public Land Survey	t <u>27N a 7W</u>	H-9	<i>A</i>
		T R	·	dean Hace REG OF DEFOS
		T R		PEG DE DECOS
		T R	····	The Contract of the Contract o
2.	Property Controlling	\$ T R		
_	in Section	S T R		
<b>J</b> .	Miscellaneous Property in Sec.	S T R S T R	i	Register of Deeds Stamp & File Number
	Froperty in Sec.	V		
4.	Lot No, Re	corded Plat		ABCDEFGHIJKLM
				2 - 6 - 5 - 4 - 3 2 - 1 - 1
			•	3
	ENFEMIE EMBRIED	to a first of account of DEVC 1	20 at 20	9 7 7 8 9 9 10 11 12 12
ι, do	bereby certify that under requ	ئــــــــــــــــــــــــــــــــــــ	6 , 19 <u>93</u> , . of 1970, the corner points mentioned	5
in I	ines 1 and 2 above were in	conformance with regulations a	nd rules therefore as required in the	6 18 17 16 15 14 17
cur	rent manual of survey instruc	ctions of the United States Depa	rtment of the Interior, Bureau of Lander points mentioned in lines 3, 4 and 5	7
wiai abo	nagement or by a decree of a conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decree of a	8 19 20 21 22 23 24
Co	urt of Law; established, re	-established, monumented, re-	monumented, recovered, found as	9
	ressed below:			10 30 29 28 27 26 25
ИО		rners, all in the same town a	nd range, may be recorded	
	on this certificate.			12 31 32 33 34 35 36
Δ	Description of original m	innument and accessories ar	id/or subsequent restoration:	13
Λ.	•• • · · · · · · · · · · · · · · · · ·		mosti fish	
	3-29-74, J.L. F 4-1-74, J.L. F 5-17-74, LCRC	rietcher, set 1/2 letcher, fd 1/2" Liber 1 Pg 312. Fletcher fd 1/2"	re-rod, Liber 1 Pg 5	631 of Surv.
	9-11-74, J.L. 9-11-74, J.L. 4-25-83, J.L.	Fletcher, id 1/2" Fletcher, fd 1/2" Fletcher, fd 1/2"	re-rod, Liber 1 Pg re-rod, Liber 1 Pg re-rod, Liber 2 Pg	598 of Surv. 793 of Surv.
В.	Description of corner evi	idence found and/or method	applied in restoring or reestablish	ing corner:
	H-9 cor. commo Found 1/2" re- On 12-16-93 th careful and fa corner.	n to Sec. 22 & 27 rod in C/L M-72, e Kalkaska Co. pe ithful reestablis	7, T27N-R7W 7' +/- W. of N-S trees group approved the shment of the position	ee line w/ fence. he above monument as a on of the original
		•		
		•		
C.	Description of monumen	it for corner and accessories	established to perpetuate locating	g the position of the corner:
Ξ.	** •	L. d	מזכת זורכת	
	Found 1/2" re-	rod - pulled & se	et 5/8"x18" re-rod W/	brass cap in Mon. Box.
	N12E, 37.70°, 6	8" W. Pine, fd r	hail & tag SE fc.	brass cap in Mon. Box.
	S10E, 51.68',	24" Maple, fd nai	1 & tag W fc.	
	S36E, 122.98',	NE cor. garage n	olock foundation.	SATE OF MICHIGAN
				FARRIER *
				_ PROFESSIONAL @
	,			SURVEYOR O
	(0			24594
		Sun a		
Sig	ned by	- Javon	Date 12-	APOFESSION ALL
Su	rveyor's Michigan License	No. 24594	FORM	GEN STATE BOARD OF LAND SURVEYORS, JAM. 28. 1971 REVISED MAY 14. 1975 REVISED JAM., 1983
				HEA19EN AWI'' 1209

95/18