

FEB 1 8 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 RALKASKA COURTY MICHIGAN

For corners in		, , , , , , , , , , , , , , , , , , , ,	RECEIVED
KALKASKA	Located In:	Corner Code ≠#	1993 DEC 22 PM 1: 35
1993 REMONUMENTATION	1		1000 000 22 111 1- 00
Public Land Survey	T 27N R 7W	L-7	Joan Stace
·	T R		REG. DE DEEDS
	T R		o neal ar in cos
2 Propody Controlling	S T R		
2. Property Controlling in Section	STR		·
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R	l l	register of Deeds Stainp & File Humber
4 1 4 4 1			
4. LOUNO, I	Recorded Plat		ABCDEFGHIJKL
o. Trivato Olamo			2 - 6 - 5 - 4 - 4 3 - 2 - 1 - 1
	• :		3
THE CHIEF THE THE THE	27077	07	4 - 7 - 8 - 9 - 1011 - 12
		27 , 19 <u>93</u> A of 1970, the corner points mentione	
		nd rules therefore as required in th	e 18 17 16 15 14 13
		irtment of the Interior, Bureau of Lan ier points mentioned in lines 3, 4 and	
• •	· ·	of Land Surveyors or by a Decree of	20 - 21 - 22 - 23 - 24
	re-established, monumented, re	-monumented, recovered, found a	ا ا ا ا ا ا ا ا ا ا ا ا
expressed below:			10 30 29 28 27 26 25
on this certificate.	orners, all in the same town a	ind range, may be recorded	12 21 - 23 - 24 - 25 - 26
on this vertificate.	•		13
A. Description of original	monument and accessories ar	nd/or subsequent restoration:	
L-7 cor. comm	on to Sec. 13 & 2	4, T27N-R7W	
1850 GLO re-s 21.	urvey: set Hem. p	ost Hemlock 18", N3	0E, 30; Beech 10", S89E,
7-7-1899, W.S	. Merrill, Co. Su	rv., tied cor. for	survey in SW/4 Sec. 13. ng trees of Gov't
4-26-00, W.S.	Merrill, Co. Sur	v., original bearin	g trees of Gov't
Re-survey. 11-9-23, W.S.	Merrill, Co. Sur	v., one Gov't beari	ng tree stump. Hemlock
16" N27W, 21;	Hemlock 14", S30	W, 35.	ng tree stump, Hemlock
9-8-75, LCRC	C Liber 1 Pg 343. Liber 1 Pg 359.		
9-8-75, N.F.	Parker, Liber 1 P	g 703. Liber 1 Pg 770 of S	
14-4-10. 0.0.	MITCOX I. DIDE	Tilber i Pa 896 or	Surv
1977, A.L. Dr	agoo, iron rod, L	iber 2 Pg 199 of Su	ber 2 Pg 240 of Surv.
4-28-78, L.M. 4-25-79, J.L.	Gerschbacher, for Wilcox, 1" nine	und 5/8" re-bar, Li Liber 2 Pg 511 of	ber 2 Pg 240 of Surv.
	wanter, I pipe,	21201 2 19 311 01	, and the same of
	•		
	i		•
B. Description of corner e	vidence found and/or method	applied in restoring or reestablis	shing corner:
			•
L-7 cor. commo	on to Sec. 13 & 24	, T27N-R7W	menton 2/ North of
Found 1" Galv:	inized pipe:'X 48" Kettle Lake road.	GLO witnesses fell	center. 2' North of l in road cut area.
On 12-16-93 th	ne Kalkaska Co. ne	er group approved i	cne apove monument as a
careful and fa	aithful perpetuati	on of the position	of the original corner.
C. Description of monume	nt for corner and accessories	established to perpetuate locati	ng the position of the corner:
L-7 cor. comm	ion to Sec. 13 & 2	4, T27N-R7W	center - pulled same and
Found 1" Galv	inized pipe x 48"	w/ 1/2" re-rod in	center - pulled same and
N18E, 33.90',	18" Beech, fd.	ap 0.0 below surfa	ice.
N60E, 57.97',	30" Hemlock fd.		OF MO
S23W, 61.27',	12" Hemlock set.	ap 0.6' below surfa	ANTE OF MICHIGAN
, , , ,	:		EUGENE D.
	1	•	* FARRIER *
	:		PROFESSIONAL SURVEYOR O
			₩ No.
Ø			24594

95/6

Surveyor's Michigan License No. 24594

RAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983