j	ŗ.	B	1	Å	1997
	A	3.5	.1.	-2	10000

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For co	orners in	SSION		ement of Act 74, Mich. P. BUNTY REMONUMENTATION		\	S Reco
	Kent (County)		ated in: Caledonia	Corner Code #		哥 云	TATE CEIVE DEC
	(County)		Township			9 76	27 DE C
1. F	Public Land Survey		5N R 10W	D-10		360	
			R	Manual Landon and Tarana and Tara			CHICAN KENT RECORD
2 -	Duan auto Cantuallina	T.	R	D. C. Mariana		, <u> </u>	5
	Property Controlling Section		R	Ref. Monument 1341.6' East of D-10		9614	
	Miscellaneous	s T	R		Register		p & File Number
۲	Property in Sec.	S 1.	н				
4. L	ot No,	Recorded Plat				BCDEF	: в н і ј к г
5. P	Private Claims		:		2		
					3	6 5 4	3-2-1
1	Randy Kolehouse	, in a field s	survey onOct	ober 29 19	96 , 4	- 7	10-11-12-
do her	reby certify that under re	equirements of P	.A. 74 Michigan P.A.	of 1970, the comer points mand rules therefore as require	entioned 5 -		
curren	it manual of survey ins	tructions of the	Jnited States Depar	tment of the interior, Bureau	of Land	18 17 17	5
Manag above	gement or by a decree o were in conformance w	of a Court of Law vith the rules of t	and/or that the come ne Michigan Board o	er points mentioned in lines 3, f Land Surveyors or by a Dec	#anu J	19 20 21	1 22 23 24
Court	of Law; established ssed below:	d, re-established	l, monumented, re-	monumented, recovered, for	ound as		
NOTE		corners, all in	the same town and	i range, may be recorded	10	30 26	3 27 26 25
	on this certificat	e.			11	-313233	34 35 36
A.	Description of origin	nal monument	and accessories a	ind/or subsequent restorat	ion: 13 L		
D-10	This corner was not	originally set by	the G.L.O.				
	1947 Survey	Votos	Williams & Works	s · 3/4" Iron			
	1973 L.C.R.C.		Williams & Works			•	
	· . · · · · · · · · · · · · · · · · · ·				P.A. 345 199	0 KENT CO	UNTY 12/196
					PEER APPE	ONED TOT	124/96 Huber
				•	CHAIRMAN	Jane	1-1-1-1
						/	
В.	* *			l applied in restoring or re-			- huilding
D-10	(Lakeview Villa Condithis information ± 0.	dominiums). R 10', Computed	eestablished 1/4 lir location for the C	f373 have been destroyed nes using survey informatio enter of Section is 3.4' Nor 0 using Williams & Works's	n from Williams th and 1.5' Wes	& Works (194)	7). Checks
				,			
-		-					
		2					
	The selected location	n is accepted by	me and is general	lly accepted by professional	l surveyors as th	e best available	e evidence
	of the position of the			da da	·		
C.	Description of monu	ment for corne	er and accessories	s established to perpetuate	e locating the p	osition of the c	corner:
D-10	Set Standard Kent C	ounty Referenc	e Monument	3		3111	OF MICH
			rch corner N 47° E	61.92'		still by	PANDY I
	Inside corner co		41° E 45.30' #131 S 54° W 91.9	8'			KOLEHOUSE
	,		#401 N 46° W 84.0			*	SURVEYOR S
		<i>ب</i> ر.		1 to 1	/ - /		No. 25854
Signe	d by Man	ly & K	olekans	Date	12/24/	16 " NO	ED LAND SURVE