SURVEY & REMONUMENTATION

APR 27 1995

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT REČĔĬŸĔĎ FŎŔ ŔĔĊŎŖD 94, DEC -5 AM 8: 57

LAND CORNER RECORDATION CERTIFICATE For cornCOMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

KENT COUNTY Located In: Corner Code =## (County) T_6N_R_11W 1. Public Land Survey T _____ R ___ ___ R . 2. Property Controlling in Section Miscellaneous

Register of Deeds Stamp & File Number

__ , Recorded Plat __ 4. Lot No.

Private Claims

Property in Sec.

William R. Byl , in a field survey on ... Sept. 12 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3 6 8 9 10 11 12

Description of original monument and accessories and/or subsequent restoration:

F-5	1831	GLO Kent Co. Wit.	Mullett	Set Post Mon. Box P.A. 345 1990 KENT COUNTY PEER APPROVED 12/1/94
	1968	MDOT		Witnesses given CHAIRMAN paryhulus
	1972	LCRC #343	Spicer	Mon. Box
	1984	LCRC #4097	Rosema	Set Kent County Monument
	1992	LCRC #6525	Bueche	Kent County Monument in mon. box

Kent County Monument in mon. box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Maurice J. Rosema on 10/18/84 and was recorded per LCRC #4097

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-5 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Maurice J. Rosema in place of the 4" Tile he found inside a mon. box. Said 4" Tile in mon. box checks with Kent Co. Wit., MDOT and LCRC #343.

LCRC #4097 LCRC #6525 S05°E 53.80' C/L manhole C/L top hydrant N85°E 131.70' N20°E NOO°E SW cor. hse. fdn. 96.44' Face of curb 15.23 Nail & tag curb joint S30°W 58.32 Nail & KC tag in bit. pkg. lot N10°E 90.07' Nail & tag 15" Poplar N30°W 69.00' SW cor. CB header S60°E 140.13' N85°E 131.84' S50°E C/L top hydrant NW cor. conc. base CP box 123.84' NOO°E 15.23' Face of curb S20°E NW cor. conc. sidewalk 107.793 W'ly cor. CB header S75°W 193.33 C/L Chamberlain Ave. is W. 155' m/l

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner Description of monument for corner and accessories established to perpetuate locating the position of the corner.

F-5	Standard Kent County Monument in mon.	box	
	C/L top hydrant		131.70
	Face of curb	NOO ^o E	15.23
	Nail & KC Remon. tag in bit. pkg. lot	N10°E	90.03
	SW cor. CB header	S60°E	140.107
	NW cor. conc. base for CP box	S50°E	123.65'
	NW cor. conc. sidewalk	S20°E	107.757
	W'ly cor. CB header	S75°W	193 237

C/L Chamberlain Ave. is W. 155' m/l; C/L 28th St. pavement is S. 15'

C/L bit. rd. E-W is South 15' m/l

01 0110 William Byl Registered Land Surveyor Mo. 23502

Surveyor's Michigan License No.

__ Date _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

REVISED JAN., 1983