## SURVEY & REMONUMENTATION



STATE OF MICHIGAN

APR 27 1995

For corners in

KENT COUNTY REMONUMENTATION

COUNTY OF KENT RECEIVED FOR RECORD

CO	M	M	1	S	S	į	0	١	ĵ
2 -1 4	II V	LV	n	•	•	•		F	v

LAND CORNER RECORDATION CERTIFICATE DEC -5 AM 8: 57 Filing Requirement of Act 74, Mich. P.A. 1970

	KENT COUNTY	Located In:	Corner Code #	and John of
	(County)		Comer Gode	REG. OF DEEDS
1.	Public Land Survey	T <u>6N</u> R <u>11W</u> T R T R T R		THE DELETIS
2.	Property Controlling in Section	S T R S T R	· ·	7650
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. 5.	Lot No, F Private Claims	Recorded Plat		2 6 5 4 3 2 1 1
do in cui Ma ab Co	hereby certify that under red lines 1 and 2 above were in rrent manual of survey instru- anagement or by a decree of ove were in conformance with	quirements of P.A. 74, Michigan P. n conformance with regulations a uctions of the United States Dep a Court of Law and/or that the cor th the rules of the Michigan Board	Sept. 13 , 19 94 A. of 1970, the corner points mention and rules therefore as required in artment of the Interior, Bureau of Land Surveyors or by a Decree monumented, recovered, found	ned the dand 7
NC	OTE: Not more than 4 c on this certificate,	corners, all in the same town	and range, may be recorded	11

A. Description of original monument and accessories and/or subsequent restoration:

·		_		P.A. 345 1990 KENT COUNTY
F-11	1831	GLO	Mullett	Set. Post PEER APPROVED 12/1/94
	1972	LCRC #176	Spicer	
	1974	LCRC #648	VanKooten	Iron in mon. box CHAIRMAN Trany Thuley
	1982	LCRC #3003	By1 🗄	Set Kent County Monument
	1992	LCRC #6528	Bueche	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by William R. Byl on 5/24/82 and was recorded per LCRC #3003

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-11 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by William R. Byl in place of the 1/2" Rerod he found. Said 1/2" Rerod checks with LCRC #176. No evidence of mon. box or witnesses per LCRC #648 - recorded incorrectly ??? LCRC #3003

LCRC #6528 SE cor. brick gar. N55°W 138.75 same witnesses as LCRC #3003 SE cor. brick hse.  $N05^{\circ}W$ 73.65 SW cor. fnd. hse. N25°E 114.50' plus Nail & tag P. Pole NOO°W 36.18' Nail & tag P. Pole S00°W 26.17 SW cor. conc. porch to hse. #1995 N30°W

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11 Standard Kent County Monument N55°₩: SE cor. brick garage to hse. #1991 138.72 NO5°W 73.69' SE cor. brick hse. #1997 SW cor. fnd. hse. #2011 N25°E 114.44' SW cor. conc. porch to hse. #1995 Set Nail & KC Remon. tag E. side P. Pole N30°W 82.92 SO5°W: 37.32 Set Nail & KC Remon. tag W. side P. Pole NOO°E

William R. Byi RISTORED Lac Simograph No. 23502 1.259

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983