SURVEY & REMONUMENTATION



APR 2 7 1995

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC -5 AM 9: 00

REG. OF DEEDS

. 0	KENT COUNTY	Located In:	Corner Code ≠#	
(County)				
1.	Public Land Survey	T 6N R 11W	K-9	
		T R	,	
		T R		
		T R		
2.	Property Controlling	S T R		
	in Section	S T R :		
3.	Miscellaneous	S T R ;		
	Property in Sec.	S T R		

7698 Register of Deeds Stamp & File Number

10

11

12

_ , Recorded Plat . 5. Private Claims

William R. Byl, in a field survey on _ Sept. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

script	ion of orig	ginal monument and acce	essories and/or subse	equent restoration: PA 245 4000
-9	1831	GLO Kent Co. Wit.	Mullett	Set Post Mon. Box P.A. 345 1990 KENT COUNTY PEER APPROVED 12/1/94
	1973	LCRC #433	VanKooten	1/2" Tron CHAIRMAN 704
	1973	LCRC #527	Bonnema	1/2" Iron in mon. box
	1981	LCRC #2032	Hackbardt	Set Kent County Monument in mon. box
	1984	LCRC #3952	Bonnema	Found PK Nail @ edge MH rim
	1989	LCRC #4970	Bueche	PK Nail @ edge MH rim
	1993	LCRC #6750	Roon	PK Nail @ edge MH rim

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Glen S. Hackbardt on 7/6/81 and was recorded per LCRC #2032 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-9 Found PK Nail at Easterly edge of MH rim per witnesses from above LCRC as found by Douglas W. Bonnema. Said PK Nail checks with previous measurement and angles in adjoining sections. (most of witnesses from LCRC #2032 removed during road const.)

LCRC #3952 LCRC #6750 S30°E 81.37' C/L Hydrant Nail & tag in P. Pole C/L Manhole 69.43' South Nail & tag in P. Pole 58:88 Exxel Iron at walk-curb N36°E Nail & tag top guard rail post N35°E 60.27' S40°E 66.80 Exxel Iron at walk-curb Capped Exxel Iron on S/L West 25.00' SE cor. brick bldg. N24°W 175.12'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C/L Hydrant S30°W C/L Manhole S00°E SE cor. brick bldg. N24°W Nail & MDSH tag in P. Pole Nail & KC Remon. tag in P. Pole Set Nail & KC Remon. tag top guard rail post cut on MH rim 23502

K-9 PK Nail at Easterly edge of MH rim

Surveyor's Michigan License No. _

施12章 175.08' \$10°E 81.60 S50°W 74.52 By! N35°E 61.86' distanted Lan N00°E 0.45 Survegor No. 23502 1 4 美华

81.39'

69.46'

REVISED MAY 14, 1975

S10°E

\$55°W

80.867

74.45'

PER WAR

REVISED JAN., 1983