

## KENT COUNTY REMONUMENTATION

Ľ	Š	1	13	1997
*	15	1	64	1.3.7.5

## LAND CORNER RECORDATION CERTIFICATE

B Children of the second	LANL	ng Requirement of Ac	t74 Mich PA 19	70	,	
For Corners In SSIC	1 (111)	ig iveduitement of ve			188	
KENT COUNTY	Located In:	Corner Code #		in a second	5 8 8 S	(O)
(County)	Located III.	Comer code in		9	まし 三 諸島	
4.0.12.1	T8N_R	11W F-12		<i>⊳</i> /	1/2 00 517	윾
1. Public Land Survey	T R		_ 1	36	D B SA	
	T R		_	SC		≓ ₩
	TR		<b>-</b>	, ,		े हैं अंग अंग
2. Property Controlling in Section	S IR S T R		<del></del>	` q <u>/</u>	101	**
3. Miscellaneous	S TR			<b>V</b> .		
Property in Sec.	S TR		_	Register of I	Deeds Stamp & File I	Numbe
4. Lot No, Reco	rded Plat			A B C D	EFGHIJ	ΚL
5. Private Claims	+	*	<del> </del>	1		
				2 6 - 5 - 5 - 3		
Kirk Breitels	is a field current on	Sept. 9 1996 do	hereby state that under	4 7 8-	91011	  1
requirements of P 4 74 Michig	an P.A. of 1970, the com	ner points mentioned in lines	1 and 2 above were in	5		
conformance with regulations and United States Department of the	drules therefore as require	ed in the current manual of S	urvey instructions of the	6 18 17	16 15 14	- - - - - - - - - - - - - - - - - - -
that the corner points mentioned	f in lines 3, 4 and 5 above	were in conformance with the	ne fules of the Michigan	7		
Board of Land Surveyors or by recovered, found as expressed by	y a Decree of a Court of elow:	of Law, established, re-est	abilatied, monumented,	8 19 20	21 22 23	;
NOTE: Not more than 2 cor		un and range, may be serv	urded	9	<del>                                     </del>	
NOTE: Not more than 2 cor on this certificate.	ners, as in the same tow	All and range, may be reco	, idea	10 30 29	282726	;2
				11	+++++	
				12 -31 32	33 34 35	3i
				13	<u></u>	السليب
A. Description of original mo	onument and accessor	ries and/or subsequent re	estoration:		,	
1933Kent SE	iams & Works : Co. WitIr cor. brk. porc	-Stake, 2639' So on th NW 83.3' NE Iron per wit.	cor. brk. porc			
B. Description of corner ev	idence found and/or m	nethod applied in restorin	g or reestablishing co	rner:		
F-12 Found 24" In	on Rod per 193					
		d 3.7' W. from in	ntersection of	1/4 lines ar	nd agrees with	
measurements						
The Iron Rod is a the best availabl				protessional	surveyors as	
C. Description of monumen	t for corner and acces	sories established to perp	etuate locating the po	osition of the corne	er:	
F-12 Set Standard		lonument in place			de Blo	la.
SE corner t				83.40' 40.06'	The second of	
PK NE side NW corner b		(ext. W. from b		90.94'	KIRK	*
SW corner b	orick bldg. (sh	nowroom)	S80°E	67.69'	BREITELS LAND	\$ * * * * * * * * * * * * * * * * * * *
NE corner b	orick porch @ g	rade	S40°W	85.00'	SURVEYOR	
	•				30077	1° 1° '
, /					Constant of the	e ye
//	1/1/2 L			11/01	TANK S	No.
Signed by /cm	1 / me	<del>5,</del>	Date/C	/11/16	- and dead the contraction of th	

Surveyor's Michigan License No. 30077 P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/22/96
CHAIRMAN Franchischer

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14,197 REVISED JAN., 198 REVISED OCT., 199