



MAR 68 1999

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

r	or	CO	m	er	S	ŧ۲

KENT COUNTY		Located In:	Corner Code #
•	(County)		
1. Public	Land Survey	T <u>9N</u> I TI TI	R11W <u>H-2</u> R
2. Proper in Sect	rty Controlling tion	S TI S TI	<u> </u>
3. Miscel	laneous rtv in Sec.	S TI	R

10918

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat	
5. Private Claims		

Kirk Breitels Aug. 14 . 19⁹⁸ do hereby state that under in a field survey on _ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	<u> </u>	С	D E	: F (3 H	IJK	L
1							
2	<u></u> 6∙	+	-5—	<u> — 4 — </u>	(3)	— ż —	— i —
3	\vdash	_ _	_				
4	7.		- 8	 9	10-	11	1,2_
5	-			-			<u> </u>
6	18		 -1 <i>7-</i>	16	 15 	14 1	13-
7						 	
8	19		-20	21	2,2	23	24-
9	\vdash		-				
10	o⊱—3o	-	-29-	28	27—	26-	2 ₅
1	1		+				
1:	23 1.		-32	33	34	35	3 6
				l l		l	

A. Description of original monument and accessories and/or subsequent restoration:

H-2 1837

GLO

Consumers Power Co.

1968 1971 Williams & Works Not Set

Intersection of 1/4 lines

Computed Intersection of 1/4 lines (No Iron Set)

1976 LCRC #1010 Nederveld Set RR Spike at Intersection of 1/4 lines

T. Pole SSW 26.78' 22" Maple SW 51.04' 32" Maple NW 58.60' C/L blktp. rd. N. 2.8'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-2 Found RR Spike per LCRC #1010. Also found Rerod with broken cap (don't know who's) 1.8' E. of RR Spike. Also "Intersection of 1/4 lines"- different measurements - by Consumers Power Co.

These three locations (all on E-W 1/4 line ±) for this were placed at the Intersection of 1/4 lines ± using three different North 1/4 corners. The Easterly of the three Irons found at the North 1/4 corner was deemed the best evidence for the corner by peer group - LCRC #9592. Said third Iron at the North 1/4 corner was used by Williams & Works and Consumers Power for their computed Intersection of 1/4 lines.

The RR Spike per LCRC #1010 has been used in surveys by MVK (Nederveld), Hackbardt, Roosien, All Points. This RR Spike is 2.6' W. of N-S 1/4 line as Monumented. Using this location does not greatly affect the surveys by Consumers Power Co. (E-W strip along N. 1/8 line across entire Section) or that of Williams & Works (NE 1/4 NE 1/4)

The RR Spike per LCRC #1010 is accepted by me and is generally accepted by professional surveyors as the best

available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-2 Set Standard Kent	County Mor	nument in place	of the RR Spike per	LCRC #1010.

Nail & KC Remon. tag S. side 36" Maple

Nail & KC Remon. tag N. side 24" Maple

Nail & KC Remon. tag SE side 14" Beech

Nail & KC Remon. tag SW side 16" Ash

C/L 1" dia. hole in top of N. end of W. 10' CMP

C/L E-W asphalt road is N. 2'

N60°W 58.35

S75°W 50.54'

S45°W 54.76 S25°E

35.66 N75°E 86.72'

P.A. 345 1990 KENT COUNT

PEER APPROVED

CHAIRMAN

FOLARO

OF MICH

KIRK

BREITELS

LAND

SURVEYOR

Surveyor's Michigan License No.

30077