For corners in

MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF	98 OCT -7	STATE OF RECEIVED
DEEDS	AM 10: 15	WORKECOND OF KENT OF KENT

KENT COUNTY Located in: Corner Code # 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

10687Register of Deeds Stamp & File Number

l. Lot No	, Recorded Plat	
5. Private Claims		

Kirk Breitels 1998 June 30 in a field survey on do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

•	<u>A</u>	B	C	D	Ε :	F (5 1	Η	Íι	J]	K J	,	ŀ
1		é—	<u> </u>	ļ 5	_	4 —		Ĭ ∍	-0	2)		 1 —	_
3			ļ					 	Ľ	<u> </u>	ļ		_
4	-	-	╁	8	-	9—	<u> </u>	0-	-1	1	 1	2—	_
5		-	 	<u> </u>		_			\vdash		<u> </u>		
6	—— <u>1</u>	! 8 	 - :	ļ'7—	-1	i 6 I	-1	5	<u></u>	 4 -	 1	3—	_
7		┢	 	-	 			 	ļ		_	H	
8	1	 9	 	20	2	! !1—	<u> </u> -2	22	2	3	2	4—	_
9		_	<u> </u>	-	-		_	ļ	·				
10	-3	ļo—	 - -	! 29	2	! 8——	<u> </u>	 7	2	6	 2	5—	_
11	_	-		├-	 			\vdash	-			_	
12	<u> </u>	1	-3	32—	—3	3	3	4	 3	5— 1	з	6	•
17	Ľ				ł	L	l	L .					

A. Description of original monument and accessories and/or subsequent restoration:

J-2 1837 **GLO** 1968 Kent Co. Wits.

Not Set

1/2" Rod in Mon. Box

MBT NNE 34.54' MBT SSE 29.18' F.P. NW 28.44' PEER APPROVED 7/23/98 CHAIRMAN Jany Truber

P.A. 345 1990 KENT COUNT

1971 Williams & Works RR Spike in Mon. Box (on E-W 1/4 line) 1977 LCRC #1059 Bonnema

Mon. Box

MBT Pole SSE 30.90' MBT Pole NNE 36.74' PK in C/L Edgerton Ave. (N-S) East 50.15'

1980 LCRC #1347 Bonnema Mon. Box Same witnesses as LCRC #1059

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-2 Found Large Spike in Mon. Box per one remaining witness:

Found PK Nail in C/L Edgerton Ave. (N-S) East 50.17'

Said Spike is less than 0.1' S. and less than 0.1' E. of intersection of 1/4 lines and has been used in surveys by Williams & Works, Exxel, Hackbardt, Hay and Consumers Power.

The Spike in Mon. Box. is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-2 Set Standard Kent County Monument in Mon. Box in place of the Large Spike.

Nail & KC Remon. fag E. side 18" Aspen N00°E 96.30 C/L Telephone Manhole N45°E 136.56 Cut "X" in top of curb (near East end) S75°E 96 57 Nail & KC Remon. tag E. side P. Pole S15°E 36.40 PK Nail in C/L Edgerton Ave. (N-S) East 50.17 On C/L Indian Lakes Rd. (E-W) ±

OF MICHIO KIDK BREITELS LAND SURVEYOR 30077 LAND SU

30077

9/25/28

Surveyor's Michigan License No.