\$7 (M)

SECTION

## KENT COUNTY REMONUMENTATION

<u> </u>				
\$2.VV	LAN	O CORNER RECORDATION C	ERTIFICATE ,	8 77 S
For corners in	Filir	ng Requirement of Act 74, Mich	i. P.A. 1970	
KENT COUNTY	La sada di las		·	
(County)	Located In:	Corner Code #		, <b>or</b> 544
1. Public Land Survey	T-9N R	11W M-8	当炒	
2.1 abilo Land Ourvey	TR			co Carres
*\$ *}1	T <u>9N_R</u>			<b>ઝ</b> 공 조
2. Property Controlling	TR S T R			
in Section	S TR		A 60 30	
3. Miscellaneous Property in Sec.	S 1R			583
, 15p01.y 500.	·		Register of Deed	s Stamp & File Number
4. Lot No, Recor	ded Plat			
5. Private Claims			A B C D E 1	FGHIJKLI
			2 6 5	4 - 3 - 2 - 1 -
Kirk Breitels	•	Inn 20 00	3	
t	, in a field survey on in P.A. of 1970, the com	Jan 28 , 19 98 do hereby state points mentioned in lines 1 and 2 about	that under 4 7 8	9-10-11-12-
conformance with regulations and	rules therefore as require	ed in the current manual of survey instructi	ions of the 5	
hat the corner points mentioned	in lines 3, 4 and 5 above	fanagement or by a decree of a Court of L. were in conformance with the rules of the	Michigan	6-15-14-13-
Board of Land Surveyors or by ecovered, found as expressed be	a Decree of a Court of How:	of Law; established, re-established, mor	numented, 7	21 22 23 24
NOTE: Not more than 2 com	nore all in the come tou	n and range, may be recorded	9	
on this certificate.	icis, as in the same ton	m and range, may be recorded	10 30 29 2	28272625
		•	11	
			12 31 32 3	3 34 35 36
A Danadakan Fadalari			13	
		ies and/or subsequent restoration:	P.A. 345 1960 K	الم الراب ب
M-8 1837 GLO 1959 Kent Co. W	Brookfield	Sct Post Mon. Box	PEER APPRQYE	02/19/98
1973 LCRC #598		½" Solid Iron in Mon, Box	CHAIRMAN	weighther
1979 LCRC #129		½" Iron in Mon. Box		
1980 LCRC #138 1981 LCRC #198		Mon. Box Set Kent County Monument in	Mon Boy	
1994 LCRC #70	65 Byl	Kent County Monument in Mo	on. Box	
The position of this	corner was previous	ly approved by the Kent County Re recorded per LCRC #1984.	monumentation Peer Group, mo	numented
B. Description of corner evid	dence found and/or m	recorded per LCRC #1984. ethod applied in restoring or reestabl	lishing corner:	
M-8 Found Kent County	Monument (Harrison	n) per wits. from above LCRC as so	et by Robert J. Jonker in place of	f the ½"
LCRC #1984	found in a Mon. Box	x. Copper Conduit checks Kent Co LCRC #7065	. Wits. and LCRC's #598, #129	0, #1398.
Nail & Remon. t	ag P. Pole S84°W	61.41' Nail & Remon. tag P.	Pole S84°W 64.41'	
	ag P. Pole N28°W 1 ag T. Pole S16°E 1			
NE corner garage	_	U	ump T. Pole S16°E 138.73' S50°W 129.95'	
Old C/L West 7.				
C/L traveled way		and is generally accepted by profes	cional curveyore or the heet avoi	lahla
evidence of the posi	ition of the original c	orner	sional surveyors as the best avai	lable
		sories established to perpetuate locat	ing the position of the corner:	OF MICH.
M-8 Standard Kent Coun Nail & KC Remon.		n. Box S84°W 61,41'		OF MICHIGAN
Nail & KC Remon.	tag W. side stump T.	Pole S16°E 138.73'	# 3)	KIRK BREITELS
NE corner garage	too SW side P. 1	S50°W 129.95'		KIRK BREITELS LAND SUBVEYOR
Nail & KC Remon. C/L N-S asphalt roa	tag SW side new P. I d is 5' West +	Pole N25°W 120.30'	\$ * i	SURVEYOR
			sional surveyors as the best avai	30077
				4 76 47

2/19/98 30077 Surveyor's Michigan License No.\_