
\$2.00	MAR 08 1999	KENT C	OUNTY REMON	NUMENTATION		10
For corners in	SECTION	LAND CORN Filing Requ	NER RECORDATION IN THE RECORDATI	ON CERTIFICATE Mich. P.A. 1970	REG.	STATE COUNTY
KENT COUNTY (County)	Located	ln: Co	Corner Code #		9 / /	4 25 25 25 25 25 25 25 25 25 25 25 25 25
1. Public Land Su	•	T <u>9N</u> R <u>12W</u> T R T R	<u>I-3</u>		DEEDS	8: 29
Property Contro in Section Miscellaneous Property in Sec.	S	TR TR TR			10470	
4. Lot No, 5. Private Claims _	Recorded Plat			·	c D F F C	amp & File Number

I, Kirk Breitels , in a field survey on Jan. 6 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the latest of the latest product of the latest production of the latest p United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration;

			and an authorist subsequent restoration:	
1980 1982	GLO Kent Co. Wits LCRC #1325 LCRC #2938 LCRC #8298	Whitcomb Nelson Merdzinski	Set Post 3/4" Iron 3/4" Iron Rod Set Kent County Monument Kent County Monument	P.A. 345 1990 KENT COUNTY PEER APPROVED 2/19/98 CHAIRMAN TOWN THE LEVEL

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John A. Merdzinski on 4-15-82 and was recorded per LCRC #2938.

Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I-3 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by John A. Merdzinski in place of the 3/4" Solid Iron over ± a 2nd 3/4" Iron he found. Both Irons check with Kent Co. Wits. and LCRC #1325.

"X" cut S, end conc. culv.		LCRC #8298	The state of the s
"Y" out M and	S85°W 103.7	8' "X" cut S. end conc. cu	ly \$050W 102 25
"X" cut N. end conc. culv.	N70°W 93.7.	5' "X" cut N. end conc. cu	IV. 303 W 103.75
"X" cut S. end cone. culv.	N20°W 103.6	0' "X" cut S. end conc. cu	IIV. IN/U"W 93.75"
Nail & Remon. tag P. Pole	N45°W 81.0	D' Nail & Remon to D. D.	IV. INZU W 103.60'
Nail & Remon. tag 30" Walnut	S20°E 68.43	· Your or remon, tag P. P.	ole N45°W 81 00'
		B' Nail & Remon. tag 36"	Walnut S20°F 68 52'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available c. Description of the position of the original corner.

petuate locating the position of the corner:

Tage 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	s establis	hed to nei
"X" cut on S. end conc. culvert "X" cut on N. end conc. culvert "X" cut on N. end conc. culvert "X" cut on S. end conc. culvert Nail & KC Remon. tag SW side P. Pole	S85°W N70°W N20°W	103.75' 93.75' 103.60' 81.00' 68.52'
1100	25	

Surveyor's Michigan License No.

OF MICHIG BREITELS LAND SURVEYOR 30077