

For corners in

SECTION

## KENT COUNTY REMONUMENTATION

## Έ

LAND CORNER RECORDATION CERTIF	CAT
Filing Requirement of Act 74, Mich. P.A.	1970

		9	つのつっ
		9 DEC	mo
538			4 - Table 1
ĊΣ	1	•	二二二
, may	<u>, 89- \</u>		≕ مہیں ۔۔۔
97E		CR	
700 Car	- 1. C.		$\neg \cap \subseteq \cdot$
<u> </u>		77.70	35778
SUE		<u> </u>	
53			- <del> </del>
0,		$\circ$	III
			خواسه بسر
		C 23	<u> </u>

KENT COUNTY Located In: Corner Code # Tyrone Twp. 1. Public Land Survey T10N R 12W 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

11610Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat	
5. Private Claims		

Kirk Breitels Nov. 2 , 19 $\underline{99}$  do hereby state that under in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

, A	15	С D .	5 f	a H	ION	L
2 -	 -6				- <b>(</b> 2 <b>)</b>	
3	Ĭ				9	
	ļ	8	 9		ij	
4	_ <u> </u>		<u></u>	10 		12 
5 -						
6 -	18 	17—	—16—i	—15— 	14	13 
7	<b>-</b>			١ .		
8 –	19 	20	<u> </u>	22-	23	24
9 -						
10	–3o—	2 9	<u>     28                               </u>	—2 <sup>'</sup> 7—	2 <del>6</del>	2/5
11	_					
12	_31	32	33	34	35	—3 <mark>6</mark> —
13						

A. Description of original monument and accessories and/or subsequent restoration:

J-2 1837 GLO

Williams & Works Kent Co. Wits

Not Set

No information

No information

P.A. 345 1990 KENT COUNT

PEER APPROVED 12/62

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;
  - J-2 Established Intersection of 1/4 lines in field and found it to fall in the Rogue River. Established 2 locations for witness monuments. Computations for Intersection of 1/4 lines agree ± with measurments of 1983 All Points surveys.

The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-2 NO MONUMENT SET AT THIS CORNER

See LCRC # 11612 for location of witness monuments.



30077