SURVEY & REMONUMENTATION

JAN 2 1 1998

SECTION

Surveyor's Michigan License No. _

		IER RECORDATION CER trement of Act 74, Mich.		
For corners in	rning nequi	rement of Act 74, wich.	REGISTER'S OFFICE	
Keweenaw	Located In:	Corner Code ##	County of Kewcenaw	SS
(County)			Received for Record, the	30th
•	T 58N R 29W	1-11	day of December	10 19 97
 Public Land Survey 	1 20M 5 20M	MC 14	at 10:00 o'clock A M.,	
•	T 58N R 29W	/ HC 14	in Liber / of	
	T R	<u> </u>	on page 175	
	T R		Julie Carlson,	Diputer
2. Property Controlling	S T R			egister of Deeds
in Section	S T R			
3. Miscellaneous	S T R		Register of Deeds Stam	np & File Number
Property in Sec.	S T R			
4 1 .1 11 -	Recorded Plat	•		
5. Private Claims	Necorded Flat			
o, Tivato Olamo			2 6 - 5 - 4	1321
			3	┈┤┈┧┈┧┈┧╸ ┼╾┼╾
			4 - 7 - 4 - 6	10-11-12
John Haataja	, in a field survey on	11/13 19	97, 5	
do hereby certify that under re	equirements of P.A. 74, Michigan P.	A. of 1970, the corner points me	ntioned 6 19 17 17	6-1-15-14-13-
in lines 1 and 2 above were	in conformance with regulations	and rules therefore as require	din the	
current manual of survey inst	tructions of the United States Dep f a Court of Law and/or that the cor	ner points mentioned in lines 3.	4 and 5 8 19 20 2	32 - 32 - 34 -
ab aug ivoro in conformanco u	with the rules of the Michigan Board	d of Land Surveyors or by a Dec	ree of a and a line in the	
Court of Law: established.	re-established, monumented, re-	e-monumented, recovered, fo	und as	
expressed below:		: \	10 30 29 2	8272625
NOTE: Not more than 4	corners, all in the same town	and range, may be recorde	ed 11	
on this certificate		•	12 31- 32- 3	3343536
:	3		13	
A. Description of origina	monument and accessories a	and/or subsequent restorati	on:	
I-11 Wood post	set in 1847	MC 14 Wood	post set at 6' above	watermark in
Cedar 10" \$70°	F 16LKS	1847.	•	
Cedar 12' N55°	W 23 LKS	Y. Pine 12"	S70°W 70LKS	
Cedar 12 Nov	. Kline placed	Fir 6" Nort		
can surveyor w	this corner on		•	
October 6, 195	2			
october 6, 195	2.			
	*			
	:			
	evidence found and/or metho	d applied in restoring or rec	establishing corner:	
		MC 1/1 No.	evidence of corner four	nd. Set MC
I-11 Found iro	n pin knocked over.	on Section	line between Section 2	26 & 35 at
Reestablished	corner at record	high watern	ark.	
	pin at 1/16 corner	nigh watern	W1 **	
to the East.		* · · · · · · · · · · · · · · · · · · ·	4.5 f	
			•	
	:			
	•	•	Ratified by	Peer Group
•	:		In accordance	with P.A. 345
			Co. Rep.	tubble
:	:		co. Rep. Art	7
•		,	Date	15/47
	•	•	r .	
		o octablished to pernetuate	e locating the position of the co	rner:
C. Description of monur	ment for corner and accessore oin with brass cap	MC 14 Set	1" pipe with brass ca	p
4" Balsam N19°	эн эт то!	12" Spruce	S75°W 44.90'	
6" W. Birch No	0 K 0 F 1 B 31 1	15" Spruce	N76°W 9.23'	FREBLAR BAR
5" Balsam S47°	°E 10.48'	10" Balsam	N42°E 17.80'	ZE MICHI
14" Cedar S19	°W 48.62'	12" Spruce	N84°E 45.84'	JOHN I.
14 CEUAT 313	, 10106	•	£ 45 }	CHAATAJA
			en f	. 1 2
			2.81	SURVEYOR =
			200	NO.
	•	Land Control	4.4	19833
•	:		13 M	
()		•	****	LAND S
7	(Landonia	Date	12/30/1997	LAND SULLEY
Signed by	10000	Date		
Surveyor's Michigan Lice	anse No		FORM APPROVED BY MICHIGAN STATE BOAR	ND OF LAND SURVEYORS, JAN. 28, 1