AUG 2 2 1995

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74	, Mich. P.A. 1970

For corners in COMM	155(0)	
Kalamazoo	Located In:	Corner Code ##
(County)		
Ross Township  1. Public Land Survey	T 1 S R 9 W	D-13
	T R	
	T <u></u> R	
•	T R	
2. Property Controlling	S T R	
in Section	S T R	
3 Miscellaneous	STR	



Register of Deeds Stamp & File Number

CDEFGHI

	Public Land Survey	T 1 S R 9 W	D-13
		T R	
		T <u></u> R	
	•	T R	
2.	Property Controlling	s r R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S R	
		Descripted Dist	
4.	Lot No , }	Recorded Plat	

Private Claims \_\_ 1 1303 LIBER

September 19 Robert E. Snell , in a field survey on \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1825: U.S. Government Survey; Set 1/4 Section Post.

9" 40½° 54 Lks North East W. Oak 9" 47½° 82 Lks North West W. Oak

1883: F. Hodgman, County Surveyor; All traces of bearing trees gone. Sighted the Town Line East and West and in that line in range with fences North. Found stake hole with rotten wood put 1' of stone in bottom and 2' earthen post over and marked.

10" North 58° East 90⅓ Lks 10" 64 3/4° East 96½ Lks Hickory South

1956: Wilkins & Wheaton Engineering; Found tile. 18" Hickory N 89° W 77.5' In fence line to N Description of corner evidence found and/or method applied in restoring or reestablishing corner: 6" Oak S 79° E 96.0' 1994: Found monument box on South edge of concrete road. Found ½" x 12" iron inside.

Below iron, found second iron (½" x 24"). Found tile 24" below surface along side of 24" iron.

THIS L.C.R.C. IS RECORDED TO CORRECT ERRORS IN L.C.R.C. LIBER 1, PAGE 1193 IDENTIFIED IN ERROR AS E-13.

RATIFIED BY KALAMAZOO COUNT REMONUMENTATION PEER GROUP 11-17-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 Section 32, T. 1 S., R. 9 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on November 17, 1994. Found 3" round tile 24" below surface as called for in 1883 remonumentation by F. Hodgman and is accepted as a careful and faithful perpetuation of the original corner's position. Placed 20" Harrison monument over tile in existing monument box.

S 60° W 103.41' Monument Box on S.Edge 14" Oak PK Nail in North Side 54.35 Concrete Pavement 12" Cherry North PK Nail in East Side In line w/fence to North Exist. Nail/Tab in North Side Telephone Pole S 42° E 33.01 Fence to Southwest 88' N 50° E 166.83' PK Nail in Northeast Side Power Pole

Signed by	Offert ?	full	' Date _	3-7-	95	

Surveyor's Michigan License No. \_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983