SURVEY & REMONUMENTATION

JUL 2 3 1997		LIBER	2PAGE	129
For corners in Richland Twp.	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	<u> </u>	97 [STATE COUNTY RECEIV
	cated In: Corner Code #	CLERK -	MAY 16	STATE OF
Public Land Survey	T 1S. R 10W. E-9 T R T R	REGISTE	PII 3	MICHICA KALAMA:
in Section S	T R	≂ ફૈ	- -	GAN AZOO CORD
	T R Regi	ister of Deeds	Stamp & I	File Number
Property in Section S, Recorded Pl	_T R Reg i		Stamp & I	File Number
Property in Section S	_T R Reg i		Stamp & I	H J K L N
Property in Section S 4. Lot No, Recorded Plance 5. Private Claims 6. IWM Job No. 26689 I, in a field sure do hereby certify that under requirements of	_T R Reg i		E F G	File Number H
Property in Section S 4. Lot No, Recorded Pl. 5. Private Claims 6. IWM Job No. 26689 I. Allen H. McMachen, in a field su do hereby certify that under requirements of in lines 1 and 2 above were in conformance manual of survey instructions of the Un Management or by a decree of a Court of L. 5 above were in conformance with the rules.	rvey on March 31 , 19 97 , P.A. 74, Michigan P.A. of 1970, the corner points mentioned		E F G 16 16 21 22 28 28	File Number H

1827 - John Mullett, D.S. Set post corner to Sec. 20, 21, 28 & 29 Wh. Oak 36" N. 80° W. 12 lks.

Y. Oak 10" N. 46° E. 29 lks.

1887 - F. Hodgman, C.S.

"Found stake and stones in place and bearing trees of resurvey standing. Set post"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Description of original monument and accessories and/or subsequent restoration:

Found iron rod in monument box. Removed iron and excavated inside box and found clay tile directly under iron rod, 1' below grade.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 4-16-1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Found clay tile is accepted a careful and faithful perpetuation of the position of the original corner. Placed Standard Sleeve over found clay tile, Accessories:

"PK" Nail in West side Twin 8" Elm N. 25° E. 102.23'

"PK" Nail in Easterly side 30" Chestnut S. 40° W. 60.06'

"PK" Nail in N.E. side 16" Locust N. 35° W. 41.61'

Nail & Tab (found) in Northerly side Utility Pole S. 60° E. 53.70'

ALLEN H. McMACHEN PROFESSIONAL **SURVEYOR** No. 16935 PROFESSIONAL

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983