REMONUMENTATION

クラ

as expressed below:

on this certificate.

Pole #7585 N. 35° E. 39.2'

MAY 28 1997

COMMISSION

STATE OF MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE SEP 9 PM 3 5

Ea	or corners in Cooper Town	nship Filing Require	ement of Act 74, Mich. P.	A. 1970							
	Kalamazoo (County)	Located In:	Corner Code #	Jan.	تريت	Yes	مستوس	/			
1.	Public Land Survey	T 18. R 11W.		CLERK		_	-				
		T R T R T R		LIBER		2PAG	E 0	59			
2.	Property Controlling in Section	S T R S T R									
3.	Miscellaneous	S T R		Register of	Deed	is Sta		File I	Numi	ber	
	Property in Section	S T R		Trogister of			p w				
4.	Lot No, Re	ecorded Plat		A	вс	DE	FG	н	l J	ĸ	Ĺ
5.	Private Claims							Ţ			Ţ
6.	IWM Job Nos. 24071, 24	991, 27425 & 27585		3	,	3					12-
			, 19 A. of 1970, the comer points men			1	1	+	H	+	+
in i	ines 1 and 2 above were in co	onformance with regulations and	rules therefore as required in the o	current	8	17	-16	15 		\perp	13-
			nent of the Interior, Bureau of orner points mentioned in lines 3,		9 💮	20	-21	-22	23		24-
			oard of Professional Surveyors of		ĽĽ.	ĨL	<u>i</u> L	Ī	آ		Ĩ

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

 1827 - John Mullet, D.S.
 1940 - County Surveyor

 Set ¼ Section post
 Placed iron on bi-section

 W. Oak 12" N. 17° 27 lks
 (2652.2' S. of Northeast corner)

 Y. Oak 14" S. 19° W., 24 lks.
 14" Maple West 19.95'

 1931 - Kal. Co. Road Commission
 24" Maple S. 60° W. 27.88'

 Found brick, set iron-stake on top
 Fence East 22.5'

 15" Maple S. 89° W. 20.55'
 8" W. Cherry S. 20° E. 96.4'

 24" Maple S. 45° W. 29.10'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" iron in mon. box nearly on line between Northeast corner and Southeast corner and nearly midway between said corners. Iron also matches (2) of the 1940 witnesses

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
2-15-1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found ½" iron is accepted as a careful and faithful reestablishment of the position of the original corner. Removed ½" iron and replaced with Harrison Monument in mon. box, Accessories:

Nail & Tab in S. Side U. Pole N. 80° E. 37.75'

Nail & Tab in SW side 6" tulip S. 55° E. 44.12"

Nail & Tab in North Side 42" Maple S. 44° W. 28.23' (1940 wit.)

Nail & Tab in North side 36" Maple West 19.42"

Signed by WCM asks
Surveyor's Michigan License No. 16935

to 9/6/96

SURVEYOR
NO.
16935

PROFES SIONAL
SIEUE ROADD OF PROFESSIONAL SURVEYORS. JAN. 28, 1971

ALLEN H. McMACHEN

PROFESSIONAL

REVISED WAY 14, 1975 REVISED JAN., 1983