

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 19	70
For corners in COOPER TWP KALAMAZOO Located In: Corner Code #	SURVEY &
1. Public Land Survey	REMONUMENTATION'
TR	FEB 0 8 2000
2. Property Controlling S TR in Section S TR	SECTION
3. Miscellaneous S T R Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	
6. IWM Job No. 31048	2 6 5 4 3 2 3
I, Allen H. McMachen , in a field survey on May 27 , 19 99 do hereby state that under	4 - 7 - 8 - 9 - 10 - 11 - 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	5
United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and for the title corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 18 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11 32 33 34 35 36
	12 31 33 34 35 35
RE	RATIFIED ALAMAZOO COUNTY MONUMENTATION PEER GROUP 6-17-1999
B. Description of corner evidence found and/or method applied in restoring or reestablishing co	11101.
Found "PK" nail 8.24' South of a standard marker at the W¼ cor., Sec. 31, Richland Twp. (t below "PK" nail and found 60d nail 0.5' below surface in road gravel (pavement 4" thick). forming a rough triangle. The center of said triangle was directly below both found nails. From Removed bricks and dug to depth of 4' finding no additional evidence of corner. Also exca depth of 4' and found no evidence of corner.	Continued digging and found 3 bricks Found bricks were 2.7' below grade.
C. Description of monument for corner and accessories established to perpetuate locating the p	osition of the corner:
	WHAT OF MICHAEL
The position of the found nails above ring of brick is accepted as the best available evidence of position of the original corner. Placed a 30" Harrison Monument at position of found nails with monument box over, Accessories:	MCMACHEN PROFESSIONAL
Concrete plat monument West 33.02' "PK" Nail in South side of 24" Maple N. 70° E. 72.13' "PK" Nail in S.E. side of Twin 12" Elm S.32° W. 55.77' "PK" Nail in West side of U. Pole S. 18° E. 65.03'	SURVEYOR No. 16935 ROFESSIONAL SURVEYOR PROFESSIONAL
Signed by ACO. HM'Mark. Date 1	11/99 Manumum

Surveyor's Michigan License No.