OCT 0 6 1997

LIBER 2PAGE 211

	- A A A A A A A A A A A A A A A A A A A	eem			<u>-</u>	
ó	ΔΙατ	LAND CORN	IER RECORDATION CERT		2 h	ST/ COUN RECI
For —	corners in Kalamazoo (County)		Corner Code #		CLERK -	STATE OF COUNTY OF RECEIVED
1. (Public Land Survey	T <u>1S.</u> R 12V T R T R			REGISTE	F KALAMAZOO FOR RECORD
	Property Controlling in Section	T R S T R S T R			ER &	AN 1200 10 RD
	Miscellaneous Property in Section	ST R ST R		Register	of Deeds Stam	p & File Number
5. I	Private Claims	, Recorded Plat		2	6 5 4	F G H J K L M
do he in line manu Mana 5 abo	ereby certify that under a es 1 and 2 above were in ual of survey instruction agement or by a decree ove were in conformance	requirements of P.A. 74, Michigan F in conformance with regulations and ons of the United States Depart of a Court of Law and/or that the o ce with the rules of the Michigan E stablished, re-established, monume	P.A. of 1970, the corner points me rules therefore as required in the ment of the interior, Bureau of corner points mentioned in lines 3 Board of Professional Surveyors	ntioned 6 current 7 f Land 7 8, 4 and 8 or by a	-18 - 17 - 11 -19 - 20 - 2 -30 - 29 - 28	5 — 15 — 14 — 13 — 14 — 13 — 14 — 13 — 14 — 13 — 14 — 15 — 14 — 15 — 15 — 15 — 15 — 15
	on this certificate		• •	11 <u>-</u> 12- 13	31 - 32 - 33	34 35 36
1		al monument and accessories D.S., Set post cor. to Sec. 19,	•		Oak 16" N. 05°	E.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E1/4 cor. and the NE cor. of Section 30 and a variation of 6° 06'.

2638.37' from said SE corner, Sec. 19 to the E¼ cor., Sec. 19.

Found iron rod per 1972 information 11' North of fence to East and 15' North of fence to West. Found iron is also approximately 1/3 of the distance between a found iron at E¼ cor., Sec. 30 and a found "T" iron at the NE corner, Sec. 19 and very nearly on line between said corners. No evidence was found on how iron was placed or by who. Due to iron being so far North of existing fence lines and no history this iron was not used for section corner. Established Section corner by measuring between found pointed stones at SE corner and the E1/4 cor., Section 30 at 2660.94',. Ed Strong (1875) measured 2658.15' and a variation of 6°. Strong (1875) also measured 2631.42' between E¼ corner and NE corners of said Sec. 30 and a "variation" of 6° 06'. Compared current and 1875 measures between SE cor. & E1/4 cor., Sec. 30 and held that proration against Strongs 1875 measure of 2631.42' between E1/4 cor., and NE cor. Producing a distance of 2634.18'. Established East-West position of corner by turning angle of 180° 06' at E¼ cor., Sec 30 in the Western quadrant matching Strong's "variations". Dug extensively in this area and found 4 baseball size stones directly below position described above. Stones found were the only stones located in all excavation and the same size as those found around the large pointed stone recovered at the SE cor., Sec. 30.

 $\underline{1875}$ - Ed Strong, C.S., "Apple 5" S. $40\frac{1}{2}$ ° E. 76 lks. stone", Shows on map measure from S.E. cor., Section 30 to E1/4 cor., Sec. 30 at 2658.15' and "variation" on said line of 6°. Also shows measure of 2631.42' between said

1972 - Consumers Power Company, Shows SE corner, Sec 19 as a found corner and shows measure of

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

The above described corner location was accepted as the best available evidence of the position of the corner. Placed Harrison Monument at said above location with Mon. Box over, Accessories:

Nail & Tab in Northwesterly side U. Pole N. 40° E. 60.45' Nail & Tab in Northwesterly side 10" Pine S. 20° E. 73.67 Nail & Tab in Northeasterly side 40" Sassafras N. 45° W. 55.60' N.E. cor. house #6985 S. 65° W. 82.50' 3.5' East of centerline N.-S. road

Surveyor's Michigan License No

ALLEN H. McMACHEN PROFESSIONAL SLIRVEYOR No. CENSED 16935 PROFESSIONAL

M /

REVISED JAN., 1983

MZ