1	
	LIBER 2PAGE 318
LAND CORNER RECORDATION CERTIFICATE	,
For corners in Kalamazoo Located In: Filing Requirement of Act 74, Mich. P.A. 1970  Corner Code #	H
Kalamazoo Located In: Corner Code #	STATE OUNTY O ECEIVE B DOT 1
	TOF 12
1. Public Land Survey T 1S. R 12W. H-11	R COSE
T R	
T R	HICHICAL ALAMAZ R. RECC PM 1 2 OISTER
2. Property Controlling S T R	CHICAN LAMAZOO RECORD N 1 28 N 1 28 N STER
in Section S T R	<b>C</b> co 307
3. Miscellaneous S T R Reg	ister of Deeds Stamp & File Number
Property in Section S T R Heg	
4. Lot No, Recorded Plat	A B C D E F G H I J K L
5. Private Claims	2 6 5 4 3 2
6. IWM Job No. 30755	3
Aller II Maldada and a second of the second	4 7 - 8 - 9 - 10 - 11 - 12-
Allen H. McMachen , in a field survey on January 6 , 19 98 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	5
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current	6 -18 -17 -16 -15 -14 -13 -
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and	8 19 20 21 22 23 24
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found	9
as expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11 12 31 32 33 34 35 36
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	,
1829 - Robert Clark Jr., D.S., Set quarter Section post, Sugar 24" N. 60° W. 6 lks., Ironwood 7" S. 70° E. 33 lks 16.13 feet Easterly of iron placed	
1903 - Ed Strong, C.S., "Found stone correct by measure. All- been held by other surveyors. Du	ig below Easterly iron and
bearing trees gone. Set crockery & brick around stone. Sugar found second iron (very old) direct 10" N. 45° E. 47½ lks., Elm 6" S. 50° W. 23 lks., surveyed the of second iron was 1.7' below road.	
West half of Southeast quarter, Section 27 into 3 equal parcels held for survey.	•
North and South (13.27 1/3 each) (876.04').  1959 - W.D. Ingersoll, R.L.S., Placed iron on line and split  1959 - W.D. Ingersoll, R.L.S., Placed iron on line and split  1959 - W.D. Ingersoll, R.L.S., Placed iron on line and split	
being 2630.17 feet from Section corners to East and to West. Nail & Tab in U. Pole S. 40° E. 80.1	/ Twin locust S. 65° E. 87.7′,
Measure West 2646.29 feet to South	
B. Description of corner evidence found and/or method applied in restoring or reestablishing	corner:
Found 3/8" pointed iron 2646.16 feet East of Southwest corner, Section 27 and 2633.	97 fact South of Contor
quarter corner, Section 27.	leet South of Center
SURVEY &	RATIFIED COUNTY
REMONUMENTATION	MAZOO COUNTY
BY NA-	DNUMENTATION , O
NOV 2 5 1998	EER GROOY /
و الله والمسروب المسروب المسرو	AMAZOO COUNTY AMAZOO COUNTY DNUMENTATION EER GROUP 3 19 198
SECTION	
D. Description of monument for comer and accessories established to perpetuate locating the	position of the corner:
E	HAMMAN OF MINISTER
Found 3/8" pointed iron is accepted as the best available evidence of the position of the original corner. Replaced found 3/8" iron with a	E A A
30" Harrison Monument with monument box over, Accessories:	ALLEN H.
And nothing the side 100 that are no proper of are	MicMACHEN PROFESSIONAL
60d nail in SW side 18" Hickory N. 25° W. 81.45' 60d nail in NW side 14" Maple N. 45° E. 74.86'	SURVEYOR S
60d nail in SW side 18" Walnut S. 45° E. 59.84'	No. 16935
60d nail in SE side 8" Aspen S. 62° W. 80.69'	SURVEYOR NO. 16935 PROFESSIONAL
	The same of the sa
immedian (000 H McMa La	19 192
urveyor's Michigan License No	HIGAN STATE BOARD OF PROFESSIONAL SALES
urveyor's Michigan License No. 76735 FORM APPROVED BY MICH	HIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAM. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983
	The state of the s