FEB 0 8 1999

2
For corners in

SECTION

Kalamazoo Twp.

2PAGE 396 LIBER :

AND (	CORNER	RECORD	ATION C	ERTIF	CATE
Filing	Requiren	nent of Act	74, Mich	ı. P.A.	1970

<u>Kalamazoo</u> Located In: Corner Code # 1. Public Land Survey 28 R G-132. Property Controlling in Section 3. Miscellaneous Property in Sec.


REGIST RECORD

Register of Deeds Stamp & File Number

4. Lot No	Recorded Plat	
5. Private Claims		

, in a field survey on Sept. 24 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate



A. Description of original monument and accessories and/or subsequent restoration:

1825: United States Government Surveyors; set post, corner to Sections 33 & 34.

Br. Oak 6" Br. Oak 8"

N. 29<sup>10</sup> W. N. 44<sup>0</sup> E.

84 1ks.

30 Tks.

F. Hodgman, County Surveyor; "Found rotton stake S. 29½0 E. 84 lks. from U.S. Bearing Tree. Put in 3 foot post with stone around and marked Wh. Oak 24" S. 590 W. 61 lks." 1885:

RATIFIED BY KALAMAZOO COUNTY

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Wilkins & Wheaton Engr. Co.; Portage corner West 25.08! 1932:

REMONUMENTATION PEER , GROUP

1949: Wilkins & Wheaton Engr. Co.; Found tile 25.13' East of Portage corner.

11/19/19

City of Kalamazoo; loss of tile during sewer construction. 1961:

P.P. 50.64' NW, P.P. 24.28' SW. (no other bearings), Portage cor. East 25.10' Found \2"x18" iron in monument box and 6" below found 3/4"x12" iron 0.07' South & 0.06' East of surface iron. Noted Portage corner East 25.16'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Southeast corner, Section 33, T. 2 S., R. 11 W., ratified by the Kalamazoo County Remonumentation Program Peer Group on November 19, 1998 and is accepted as the best available evidence of the position of the original corner. Found 12x18 iron in monument box with 3/4"x12" iron below. Lower iron is believed to have been placed after sewer construction in 1961 to replace tile set by F. Hodgman in 1885 Remonumentation Survey. Placed 20" Harrison monument in monument box in place of

•	the mortality box. In prace	אוויסווי ויט
1" Iron PK Nail in West Side PK Nail in East Side Nail/Tab in East Side	in Monument Box S. 54° W.  Power Pole N. 38° E.  Power Pole N. 20° W.  Power Pole (in conc. walk) S. 50° E.	44.60' 80.73' 64.48' 55.56'
igned by / of c. teres	Date 12-18-97	00100
urveyor's Michigan License No. 973/		·····