FEB 1 8 1994 -

## COMMISSION

For corners in

Property in Sec.

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Scarce Token	4 JAN 21	STATE OF MACHIGAN OUNTY OF KALAMAZOC ECEIVED FOR RECORD
RECIS	Am	OF KALAMAZOO D FOR RECORD
TER O	8	AM,
f	56	HIGAN AMAZOO RECORD

Kalamazoo	Located In:	Corner Code ##	
Public Land Survey	т <u>2 S</u> R <u>12 W</u> Т R	<u>I-12</u>	
	T R T R		
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous	S T R		

1 pc1092 LRER Register of Deeds Stamp & File Number

4.	Lot No ,	Recorded Plat _		 
5.	Private Claims		· · · · · · · · · · · · · · · · · · ·	 

I, Robert E. Snell , in a field survey on December 8 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

Established by U.S. Government Survey 1829 - Set Post
Bl. Oak 12" South 84°-E 67 Lks (44.22')
Wh. Oak 8" North 89°-W 74 Lks (48.84')
1875-E. Strong County Surveyor - "T" Rail from U.S. Stump.
1962-Wilkins & Wheaton Engr. Co. - plow point.

1962-MSHD-Found 8" R.R. anchor plate - plow point.

1968-Wilkins & Wheaton Engr. Co.-found rust remains of "T" Rail, placed 3/4"x3' iron & 1/2"x18" iron rod.

Iron-N 30-13' E 33.53' 10" Oak-S 080-25' E 18.5' 10" Oak-S 790-24' E 25.35' 24" Oak-N 400-51' W 30.10' Twin 8&10" Oak-S 300-06' W 27.2' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. anchor plate and 1/2"x18" iron near surface, recovered 3/4"x3' iron and rust remains of "T" rail as called for in previous surveys below surface iron. Original corner not recovered.

> Y KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 12/16/93

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - West 1/4 post Section 35, T. 2 S., R. 12 W., Ratified by Kalamazoo County Remonumentation Program Peer Group on December 16, 1993. Found 1/2"x18" iron and R.R. anchor plate near surface and found 3/4"x3' iron below and is accepted as a careful and faithful perpetuation of the position of the original corner. Removed 1/2"x18" iron and R.R. anchor plate as well as 3/4"x3' iron, placed 30" Harrison monument and placed R.R. anchor plate along side of monument.

PK Nail in E side	<i>∴</i> .	9"	Sassafras	N 14 <sup>0</sup> -30' W	1.55
PK Nail in SW side		30"	0ak	N 380 W	29.951
PK Nail in SW side		16"	0ak	S 76 <sup>0</sup> E	25.25'
PK Nail in E side		18"		S 08° E	18.20'
		00.1	~ /		E0 001

PK Nail in W side Signed by Top of R.R. cut South 12

Surveyor's Michigan License No.

REVISED MAY 14: 1975