## SURVEY & REMONUMENTATION

APR 27 1995

STATE OF MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'95 JAN 13 AM 11 50

FOI COIN	ers in				
Ka]	Lamazoo	Located In:	Corner Code ##	On meditings	
	(County)			James Jours	
1. Publ	ic Land Survey	T <u>35</u> R <u>9W</u> TR TR	C8	CLERK-REGISTER	
in Se	erty Controlling	T R S T R S T R		LBER 1 PG 1260	
	ellaneous erty in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
1 Lot 1	Jo.	Recorded Plat		3	
5. Priva	te Claims	Accorded Flat		A B C D E F G H I J K L M	
do hereby in lines 1 current m. Managem above wer Court of expressed NOTE:	certify that under re and 2 above were it anual of survey instrent ent or by a decree of re in conformance w Law; established, thelow:	, in a field survey on June quirements of P.A. 74, Michigan P.A. on conformance with regulations and ructions of the United States Departra Court of Law and/or that the corner in the rules of the Michigan Board of re-established, monumented, re-motorners, all in the same town and	of 1970, the corner points ment if rules therefore as required ment of the Interior, Bureau o points mentioned in lines 3, 4 Land Surveyors or by a Decr- onumented, recovered, fou	titioned   6	
Quarter Accessor 1861 acc 1863 E. 1883 F. Ho 1966 I.W.M	Section Postries: Yellow ressories by Strong "Stone deman "Found la Linc. accessorand stone.	Oak 16" S 40½°W 122 1k F. Stimson: W. Oak 16" e unknown". arge boulder with drill hole ies: 5/8" drill hole in headw 24" Apple East 43.0' I n, Inc. Fnd. spike 4" d	eputy Surveyor Robers. White Oak 20' N70½°E 160½ 1ks. for corner set by R. Nwall S85°W 26.23' U. p. 12" Twin Oak N60°E 44.	ert Clark, Jr. in 1826. "N 12½°E 87 1ks. W. Oak 17" N43°E 163½ 1ks. Nutting with side stones 501ks. each east & west cole S70°W 64.47' 30" Oak S75°E 46.0' 46' ine road. Accessories:	
		vidence found and/or method a accessories not recove	-	stablishing corner:	
Found ca	bin spike 6"	under asphalt patch in	road.		
Found 18	" dia. bould	er with 5/8" drill hole	directly below sa	aid cabin spike 4.5' below asphalt.	
Accessor	ies from sec	tion A above still exis	ting (new measurem	ments):	
	•	/8" drill hole in center of conc. headwall S85°W 26.33' (Headwall was later emoved in 1994 reconstruction of 38th street).			
		. nail`in 38" Apple eas		RATIFIED COUNTY	
		. in U. pole S70°W 64.4		REMONUMENTATION	
				PEER GROUP) 12-15-94	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  $\mathbb{C}8$ ,  $\mathbb{E}^{1}_{4}$  Corner Section 19, T.3S., R.9W. Found 18" dia. boulder with 5/8" drill hole 4.5' below asphalt patch directly below fnd. cabin spike. Boulder is believed to be same as called for in 1883 notes by F. Hodgeman and is accepted as a careful and faithful perpetuation of the original corner position. Removed cabin spike and placed 30" Harrison monument centered over drill hole in boulder. Placed monument box over mon.. OF MICH P.K. nail in N. face 38" Apple East 43.51' Accessories: E OF MICH

P.K. nail in U. pole S30°W 78.001

P.K. nail in U. Pole S70°W 64.49'

P.K. nail in 39" Oak S34%E 45.80'

38116 Surveyor's Michigan License No. \_

11-4-94 Date \_

No. 38116

1-4-94

FORM APPROVED BY MICHIGAN STATE BOAND BANG STATE PROJECT OF SERVICE PR VEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

HAHN LAND SURVEYOR No. 38116

REVISED JAN., 1983