FEB 0 8 1999

7 SECTION	LIBER	2PAGE 375
LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	E .	C HC
For corners in Pavilion Twp.	- 11	STATE COUNTY RECEIVE
Kalamazoo Located in: Corner Code #	CLERK	
1. Public Land Survey	- REGISTE	OF MILLOF KALL
2. Property Controlling S T R	20 3	AN IZOO ST
	Register of	Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D	E F G H I J K L M
I, Robert E. Snell, in a field survey on Aug. 12, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	7 8-	9 10 11 12
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		28 - 27 - 26 - 25
BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 4-17-1949 A. Description of original monument and accessories and/or subsequent restoration:		33 34 35 36
1827: United States Government Surveyors; set 1/4 Section post. White Oak 16" N. 10 W. 80 lks. White Oak	: 24 ^u	S. 60 ⁰ E. 60 lks.
1874: F. Hodgman, Surveyor; "stone set by E. Briggs from Watons' distance from one witness, Northwest by 2 lks." Hickory 16" N. 83° E. 115 lks. Hickory 1	_	does not agree in S. 79½°W. 135 1ks.
1888: F. Hodgman, County Surveyor; "found stone set by Nutting. Cherry 12" S. 450 + E. 64 1ks. Sycamore	Set post	." N. 75 ⁰ <u>+</u> E. 133 2/3 1ks
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1960: Acro Engineers; tile $\begin{array}{cccccccccccccccccccccccccccccccccccc$		
1963: Ingersoll; found tile. 1967: John Stack, RLS #10707; Plat of Indian Run Golf Estates L- 1/4 post Section 29. Believed to have placed plat monumen 1998: Found ½" iron pipe in concrete (plat monument), 2' below s	ıt.	
of tile laying on its side.		
C. Description of monument for corner and accessories established to perpetuate locating the position	n of the corner	
C-10: West 1/4 post, Section 29, T. 3 S., R. 10 W., ratified by Remonumentation Program Peer Group on September 10, 1998 a and faithful perpetuation of the position of the original pipe in concrete (plat monument) in place of tile set by F in 1888 Remonumentation survey. Removed plat monument and monument in its place with monument box over.	the Kalam ind is acc corner. . Hodgman placed 2	azoo County epted as a careful Found ½" iron , County Surveyor
PK Nail in West Side Power Pole N. 10 ⁰ PK Nail in East Side Power Pole S. 18 ⁰ PK Nail in East Side 20" Walnut S. 12 ⁰ PK Nail in East Side Power Pole N. 16 ⁰	' E.	29.52' 68.77' 47.97' 52.23'
Signed by Date 9734	-20.	78
Surveyor's Michigan License No. 9734		-