





NOV 2 5 1998

S	EC.	0	N

4. Lot No.

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE

Kalamazoo	Located In:	Corner Code #		_ (,	ريني	ST PEC
(County)				がいれ	ET ISI	EIV TIV
1. Public Land Survey	<u>T3S</u> R	10W E-10		NEW Y	22	599
	K T R T R			351	八哥	FOR R
2. Property Controlling in Section	S TR S TR			TO THE		ECO
B. Miscellaneous Property in Sec.	S T R			E &	ω ⊸3	
Property in Sec.	·— ·	······································	Regis	ter of Deeds S	tamp & F	ile Number

•
I, Robert E. Snell, in a field survey on May 6, 1998 do hereby state that under
, at a local servey of the
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in
conformance with regulations and rules therefore as required in the current manual of survey instructions of the
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,
recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. RATIFIED

BY KALAMAZOO COUNTY

REMONUMENTATION

PER GROUP 5/L.

A. Description of original monument and accessories and/or subsequent restoration: United States Government Surveyors; set 1/4 posts

N. 47° W. White Oak 14" 44 1ks.

N. 89° E. 32½ 1ks. White Oak 18"

1888: F. Hodgman, County Surveyor; "found stone with brick under and bearing trees of re-survey standing. Set post."

S. 45⁰ E. Hickory 10" 61 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1972: D. Ratekin, RLS#8781; L.C.R.C., L-1, P-13; 3/4" iron Steel St. Sign Post S. 30° W. 45.1' 28" | Fence Corner Post N. 85° E. 28.2' 10" | N. 60° W. 74.5' 28" Bitter Hickory 10" Pine 25° E. 78.1' 4 0ak S.

Found 3/4" iron in monument box, further digging revealed 3" round tile, top broken 1998: 1.75' North and 0.55' West of surface iron. Tile was 10" below surface of road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

West 1/4 post, Section 28, T. 3 S., R. 10 W., ratified on May 21, 1998 by the E-10: Kalamazoo County Remonumentation Program Peer Group and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile along side large stone. Tile was set by F. Hodgman, County Surveyor in 1888 Remonumentation survey. Placed tile sleeve over tile and 8" of 10" Harrison monument over and in monument box.

S. 56° E. S. 28° E. S. 16° W. 47,31 Nail/Tab in North Side Power Pole 10" Oak 15" Hickory 79.99^t PK Nail in North Side 100,991 PK Nail in West Side PK Nail in North Side N. 70° 32" Hickory 74.14 t

ofz Signed by Surveyor's Michigan License No.