MAY 1 6 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF KALAMAZOC
RECEIVED FOR RECORD

'96 APR 30 PM 2 58

For corners in Kalamazoo (County)	Located in:	Corner Code #	00 00 2 00
City of Portage	2 .		Jamed Jours
Public Land Survey	T <u>3S</u> R <u>11V</u> T R		CLERK-REGISTER
·	.T R T R		LIBER 1-PAGE 1486
2. Property Controlling	\$ T R		,
in Section	S T R		
3. Miscellaneous	S T R		
Property in Section	\$ T R		Register of Deeds Stamp & File Number
4. Lot No, F	Recorded Plat		A B C D E F G H I J K L
5. Private Claims			

I, Gary D. Hahn , in a field survey on October do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: 1827 Corner established by Deputy Surveyor Robert Clark, Jr.

W. Oak 11in. S62 W 401k W. Oak 12in. N13 E 521k

1874 E. Strong "Found hole after intersection". Y.O. 12 S27½W

1946 Wilkins & Wheaton Pl. iron from plat 24" Oak N35°W 29.0' 24" Oak N33°E 29.4' 24" Oak S6 W 34.0'

Date? I.W.M. P.P. SW. 53.38' P.P. SE. 60.05' P.P. NE. 63.80' Top NE. bolt conc. 1p. base NW. 92.00'

19/26 I.W.M. 6" oak NW. 57.60' P.P. SW. 85.05' 30" Oak SW 64.75' P.P. SE. 43.85' 1976 I.W.M. LCRC L1, P.738 iron in sleeve. 6" Oak NW. 57.60' 30" Oak SW. 64.75'

P.P. SE. 43.85¹

B. Description of corner evidence found and/or method applied in restoring or reestablishing comer: Original monument and accessories not recovered.

Found 3/4" "T" iron in mon. box. Dug a 4'X6'x4.5' deep hole. Found no other monument evidence. Existing roadway appears to have been cut down 3'+/- below existing ground in the area.

Also... "T" iron was 165.22' North of a found conc. monument in Oak Timbers Platted distance is 165'... Plat No. 1.

RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 2-15-96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner E-7, Southwest corner Section 16, T3S, R11W, Ratified by Kalamazoo County Remonumentation Peer Group on February 15, 1996. Location of "T" iron is accepted as the best available evidence of the position of the original corner. Removed "T" iron and set a 30" Harrison monument in a monument box.

Found P.K. in P.P. S60°W 85.03' Found P.K. in E. Face of P.P. S

S1°W 43.62'

Top bolt on hydrant N42°W 51.60'

Most Sly. Southwest corner of conc. block house foundation N55°E 79.48

Signed by 38116 Surveyor's Michigan License No.

Date <u>April 23,1996</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF

MANUE OF MIC HAHN LAND SUR A CHASED LAND