AUG 2 2 1995

LAND CORNER RECORDATION CERTIFICATE

For corners in	COMMISSIFILING Requi	irement of Act 74, Mich.	P.A. 1970	'95 APR 26 API 1 The
Kalamazoo (County)	Located In:	Corner Code ##	-	11 130/6
Texas Township 1. Public Land Survey	T <u>3 S</u> R 12 W T R T R	<u>K-1</u>		CLERK-ALGISTER
Property Controlling in Section	S T R S T R		LIBER	1 1296
3. Miscellaneous Property in Sec.	S T R S T R		Re	gister of Deeds Stamp & File Number
4. Lot No, 5. Private Claims	Recorded Plat			A B C D E F G H J L A
do hereby certify that under re in lines 1 and 2 above were current manual of survey instr Management or by a decree of above were in conformance w	equirements of P.A. 74, Michigan P.J. in conformance with regulations a ructions of the United States Depart a Court of Law and/or that the corrist the rules of the Michigan Board re-established, monumented, re-	A. of 1970, the corner points men and rules therefore as required artment of the Interior, Bureau ther points mentioned in lines 3, If of Land Surveyors or by a Dec	ntioned d in the of Land 4 and 5 ree of a	4 7 8 9 10 11 12 15 6 18 17 16 15 14 13 7 8 9 10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificate	corners, all in the same town a	and range, may be recorde	d	11 12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1829: U.S. Government Survey; Enter North boundary 96 Lks East of Post. Set Post at intersection of Corner Sections 1 and 2.

Wh. Oak 9" South 50° West 149 Lks Wh. Oak 9" South 82° East 511 Lks

- 1911: Ed Strong, County Surveyor; Northeast Corner stone W. Oak South 45° West 28 Lks
- 1992: Wilkins & Wheaton Engineering Company; Found "T" iron fitting old witness for Northeast Corner Section 2, Texas and 63.38 East of iron set for Southeast Corner Section 35, Oshtemo. (Government Jog=63.36').
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1993: Replaced Northeast Corner Section 2 from witnesses following sewer and road reconstruction. Original corner lost in sewer construction.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12-16-93

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- K-1 Northeast Corner Section 2, T. 3 S., R. 12 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on December 16, 1993. Found iron in monument box as replaced following sewer construction and is accepted as careful and faithful perpetuation of the position of the original corner. Placed 20" Harrison monument in monument box.

Monument in Monument Box (K-13; T. 2 S., R. 12 W.) West (MSHD) Nail/Tab in North Side (MSHD) BM Tab in Southwest Side (MSHD) South (MSHD) South (MSHD) Southwest Side (MSHD) South (MSHD)

Surveyor's Michigan License No. _