1335

COM BOSICIA

LAND CORNER RECORDATION CERTIFICATE Eiling Boguiroment of Act 74 Mich PA 1970

STATE OF MISHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

PER ONE OF PM 3 51


	Filing Requireme	shit of Act 14, which F.A.	22 Uno 52 LII o 21
For corners in Kalamazoo (County)	Located In:	Corner Code #	Jennymage
Texas Township 1. Public Land Survey	T <u>3 S</u> R <u>12 W</u> T R T R	M-6	CLERK-1.ESISTER
Property Controlling in Section Miscellaneous	T R S T R S T R S T R	**	LIBER 1 21326
Property in Section	S T R		Register of Deeds Stamp & File Number

August 29 I. Garth N. Baden , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

__, Recorded Plat_

4. Lot No. 5. Private Claims



A. Description of original monument and accessories and/or subsequent restoration:

United States Government Surveyors; Set 1/4 Section Post.

6" 45° South West W. Oak 6¹¹ 67° 21 Lks North West W. Oak

1959: Wilkins & Wheaton Engineering Company; Placed iron 24.75' South of West 1/4 Post, Section 18, T. 3 S., R. 11 W. (Portage A-6).

B. Description of corner evidence found and/or method applied in restoring or reestablishing comer:

Found 5/8" x 24" Iron in monument box. Found evidence of digging to a depth of 4' below pavement.

> **RATIFIED** BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP 6-15-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

East 1/4 Post Section 13, T. 3 S., R. 12 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on June 15, 1995 and is accepted as a careful and faithful re-establishment of the position of the original corner. Found 5/8" x 24" iron in monument box. Replaced with a 20" Harrison monument and monument box after sewer construction.

South 60° East 23.92' 36" Oak Exist. Nail/Tab in North Side Exist. Nail/Tab in South Side Power Pole North 80° East Exist. Nail/Tab (Upper Tab) in North Side Power Pole West 63.781 37.44 North 22° West 67.14' 26" Oak PK Nail in Northeast Side

auk Signed b 10679

Surveyor's Michigan License No.

Date Clas 22 1995