REMONUMENTATION			
FEB 2 6 1998		٠,	
SECTION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970	LIBER	2PAGE 218	
For corners in Wakeshma Township		€. 97	> ~~
Kalamazoo Located In: Corner Code #	CLERK	PRECEIVED 97 OCT 22	TAI
1. Public Land Survey T 4S R 9W M-01 This corner common to T R T R T R T T R T T T T R T T T T T	- RE	22 AM	OF MICHIGA
2. Property Controlling S T R	GISTER	FOR RECORD 2 AM 10 41	HOAN
Property in Sec. S T R	Register of E	Deeds Stamp & File I	
4. Lot No, Recorded Plat	BCD	E F G H I J	к г.
1 2	65-	4-3-2-	
3			
I, <u>Robert F. Snell</u> , in a field survey on <u>June 6</u> , 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with requisitions and rules therefore as required in the current manufacture in the	— j — 	91011-	12-
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	1,81,7	16-15-14	1,3
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	+ + +		
NOTE: Not more than 2 comers, all in the same town and range, may be recorded 9		-23 -22 -23	
on this certificate.		28 27 26	25
11 12	-3132	33 34 35	36
A Description of original recoverant and accounting at the state of th			
A. Description of original monument and accessories and/or subsequent restoration: 1825: United States Government Surveyors; post at corner			
Beech 9" N. 52° W. 14 lks. Beech 10" S. 80° E. 21 lks.			
1883: F. Hodgman, County Surveyor; Section 36, "3 - found larg hole in it set for corner by R. Nutting" - no tile set.	e boulder	r with drill	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
1997: Found a large boulder (2'x2'x2') with a 5/8" drill hole surface of gravel road.	in top, I	18" below	
In centerline of road intersection <u>+</u>	Þ	ATIFIED	
Telephone Pedestal N. 60° E. 26'+ BY Telephone Pedestal S. 54° W. 45.9'+	KALAN REMON PEE	MAZOO COU IUMENTATIO ER GROUP G	
P.K. nail in North side 12" Elm N. 78° E. 29. P.K. nail in South side 10" Butternut S. 50° E. 22.	by Kalamad is accessoring to 1883 or 1883 on 1	azoo County epted as a I corner. 3 survey by F.	11
P.K. nail in South side 30" Maple S. 32° E. 42.	631		

<u>75.</u> 9734

Signed by // Surveyor's Michigan License No.