FEB 0 8 1999 -

2PAGE 425 LIBER SECTION LAND CORNER RECORDATION CERTIFICATE COUNTY OF KALAMAZOC Filing Requirement of Act 74, Mich. P.A. 1970 For corners in KALAMAZOO **BRADY TWP** Located In: Corner Code # (County) CORNER COMMON WITH M-13, SCHOOLCRAFT TW 4S. R 10W. A-13 1. Public Land Survey T Ţ 2. Property Controlling in Section Ţ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section _ , Recorded Plat Lot No. 5. Private Claims Allen H. McMachen , in a field survey on November 25 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

1826 - Robert Clark, Jr., D.S.,

on this certificate.

(Survey of Brady Twp.), Intersected range line 480 lks. South of temporary six mile post. Set post at intersection corner to Townships 4 and 5 South, Ranges 10 and 11 West, Wh. Oak.9" S. 52° W. 33 lks.

(Survey of Schoolcraft Township), Post at Township corner, Wh. Oak 9" S. 52° W. 33 lks., Hickory 7" N. 481/2° E. 41 lks..

1869 - F. Hodgman, C.S., "Found stone N. 52° E. 33 lks from stump of U.S. bearing tree, set post, Maple 8" S. 44½° W. 46 lks., Elm 20" N. 45° W. 64½ lks..

<u>Date?</u> - Old Kalamazoo County Road Commission Plans, Placed iron 3.2' East of "tile" (Sec. cor.), Wits to iron rod, Elm 26" N. 48° W. 45.7', Maple 18" S. 49° W. 33.4', Elm 18" S. 46° E. 42.0'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe in mon. box in centerline believed to be iron placed by Road Commission. Measured West 3.2' and had magnetic indication of corner. Dug and found iron rod over Clay Tile ringed with stones. Tile was 1.5' below road surface.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12/17/98

C. Description of monument for corner and accessories established to perpetuate locating the position of

Found clay tile is accepted as a careful and faithful perpetuation of the position of the original corner. Placed standard sleeve over tile with monument box, Accessories:

N.W. corner of porch foundation S. 50° E. 94.07' S.E. corner of house foundation N. 55° W. 98.53' Nail & Tab in 20" Sycamore N. 20° W. 93.52' Nail & Tab in 10" Walnut S. 70° W. 56.60' 1" pipe in monument box East 3.2'

Signed by OOO M M 'M OOO Surveyor's Michigan License No. 16935

12/18/98

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

LICENSED .

REVISED JAN., 1983

MICH

9.0

ALLEN H.
McMACHEN
PROFESSIONAL
THE COUNTY OR

No.

16935

PROFESSIONAL