EURIVEY & REMONUMENTATION

7-3- MAY 28 1997

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER	2PAGE	111		
Same Carrier	'96 DEC 31	STATE OF COUNTY OF RECEIVED F		

Kalamazoo Located In: Comer Code # (County) **Brady Two** 1. Public Land Survey D9 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Starop & File Number

, Recorded Plat 4. Lot No. 5. Private Claims

I, <u>Gary D. Hahn</u>, in a field survey on <u>May 3</u>, 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

			*			
1 A	ВС	DE	FO	H	I J	K L M
2	-6-	5 -	_ 4	3	_2_	 1 -
3 -	_				<u> </u>	
4	-7	8	þ	10	 1 <mark>1</mark>	12
5				-		
6	-18-	-17-	16	1 _{.5}	14	13-
7						
8	_19	20	 21	 22	23	24_
_ و						
10	_30	29	<u> </u>	27	26	25
11						
12	-31	32	33	34	35	36
.,						

A. Description of original monument and accessories and/or subsequent restoration:

1826 South quarter corner established by U.S. Deputy Surveyor Robert Clark, Jr. Accessories: 14" W. Oak South 86 degrees East 66 links 14" W. Oak North 16 degrees West 30 links

1919 KCRC road plans for 27th St. give distance to Cen. Sec. 20 of 2653.4' and distance to Cen. Sec. 29 of 2655.9' Witness ties: R.R. iron fence cor, W. 25.8'

R.R. iron fence cor. E. 25.8' Oak 3" North 85 degrees West 25.8' Walnut 6" South 35 degrees East 54.0"

1968 I.W.M. found KCRC 1919 iron - set mon, box over iron.

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer.

Original monument and accessories not recovered.

Found 3/4" dia. 2.5' long iron rod in mon. box. Dug a 3' X 6' X 5' deep hole through gravely sand. Found no additional monument

evidence. Road does not appear to have been extensively filled.



RATIFIED BY KALAMAZOO COU REMONUMENTATION PEER GROUP 9-19-1996

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

D9, South quarter corner Section 20, Town 4 South, Range 10 West, ratified by Kalamazoo County Remonumentation Peer Group on September 19, 1996. Found 3/4" dia. rod believed to be same as referenced in KCRC 1919 road plans. This rod position is accepted as a careful and faithful perpetuation of the position of the KCRC 1919 corner. Removed rod and set a 20" Harrison Monument in mon, box. Fnd. nail in 14" Maple South 26 degrees East 53.27 Harrison mon. (cen. sec. 20) North 2653,59'

Fnd. nail in 16" Triple Maple North 85 degrees West 25.78"

Set P.K. nail in twin stump South 87 degrees East 26.40'

Set 1/2" rebar North 45 degrees West 46.36

R.R. iron fence post East 27.0 +/-

R.R. iron fence post-West 26.1 +

Signed by Surveyor's Michigan Lig Harrison mon. (cen. sec. 29) South 2654.12'

Date 12/27/96