

MAY 16 1996

COMMISSION

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD

'96 MAR 13 PM 3 42

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Kalamazoo Located In: _____ Corner Code # _____
 (County)
Schoolcraft Twp.

1. Public Land Survey T 4 S. R 11 W. A-07
 T _____ R _____
 T _____ R _____
 T _____ R _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
 Property in Section S _____ T _____ R _____

Jamie D. Young
CLERK-REGISTER

LIBER 1 1447

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Robert E. Snell, in a field survey on January 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826: Original United States Government Surveyors; intersected West boundary 117 lks. North of post. Set post at intersection, corner to Sections 18 and 19.

Ironwood 6" N. 36° E. 4 lks.
W. Ash 30" S. 40° E. 6 lks.

1888: F. Hodgman, County Surveyor; found iron, brick, and bearing tree of resurvey all in place, set post.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1951: Wilkins & Wheaton Engr. Co.; found iron, tile, brick and stone.

50" Elm S. 58° W. 18.9'
1 1/2" Iron Pipe South 36.2' in traveled center line of road
36" Sugar Maple N. 70° E. 48.95'

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
2-15-96

1974: Don Gilchrist, R.L.S. #13583; L.C.R.C. L-1, P-613 tile

18" Ash S. 30° W. 74.64'
36" Maple S. 40° E. 111.40'
Twin 12" Ash N. 10° E. 32.58'

1996: Found 3" round tile - top broken 3" below surface with brick around, East edge of concrete drive S. 70° W. 3.33' iron in traveled center line South 36.2'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-07: Southwest corner Section 18, T. 4 S., R. 11 W., Ratified by Kalamazoo County Remonumentation Program Peer Group on February 15, 1996 and is accepted as a careful and faithful perpetuation of the position of the original corner. Found 3" round tile (top broken) as set by F. Hodgman, County Surveyor in 1888 Remonumentation Survey. Placed a remonumentation sleeve over tile.

PK Nail in West Side 12" Maple S. 42° E. 2.65'
PK Nail in North Side 7" Ash N. 72° W. 25.84'
PK Nail in East Side 12" Maple N. 18° W. 9.31'
PK Nail in North Side 18" Maple S. 85° W. 44.24'

Signed by Robert E. Snell

Date 3-12-96

Surveyor's Michigan License No. 9734