REMORTMENTATION

FEB 1 8 1994

UBER 1 PG1005

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

County County Schoolcraft Township T	E D C ENA	ment of Act 14, mich. t		For corners in
1. Public Land Survey T 4 S R 11 W C-7 T R T R T R T R T R T R T R T		Corner Code ##		(County)
2. Properly Controlling S1 H	ALAMA OR RECORD OF RECORD	C-7	T R T R	Public Land Survey
	\ B RD			2. Property Controlling in Section
3. Miscellaneous S T R R Register of Deeds Stamp & File Num Property in Sec. S T R	Register of Deeds Stamp & File Number			• • • •
4. Lot No, Recorded Plat A B C D E F G H I J	A B C D E F G H I J K		Recorded Plat	

I, John G. Kester , in a field survey on July 30 , 19 93 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:

 Corner Post established by U.S. Government Deputy Surveyor Robert Clark, 1826,
 Post in Mound in Prairie no accessories. Survey by E. Strong, 1870, Found Stake
 and Stone Planted Stone 16" long with smaller stone around, Accessories: Maple
 3" N56½ 106½, Maple 3" N17½ 159. Resurvey by F. Hodgeman, 1889, Found Stone
 set for Corner S56½W 106¼ Lks from Maple Bearing Tree. Set Post (Solid Clay Tile),
 Accessories: Maple 6" S59E 86 Lks, Maple Bearing Tree N56½ 106¼ Lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

 Original Corner Post and Accessories not recovered.

 Found Monument Box over 3/8" iron rod over 3/4" pipe with brick & stone around over Solid Clay Tile with "X" on top as called for in 1889 Resurvey by F. Hodgeman, Accessories gone.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
8-19-93

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-7, Section Corner 17,18,19 & 20, T4S-R11W, Ratified by Kalamazoo County Remonumentation Program Peer Group on August 19, 1993. Found Solid Clay Tile with "X" on top as per 1889 Resurvey and is accepted as a careful and faithful perpetuation of the position of the original corner. Removed existing Monument Box, iron & pipe. Placed 20" Harrison Monument above Tile and Placed Monument Box over Corner.

Set P.K. Nail in P.P. N 45 W 48.12' Set P.K. Nail in 20" Walnut S 50 W 56.63' Set P.K. Nail in P.P. N 22 E 99.66'

T/Bolt	Hydrant	S 25	E	72.80
--------	---------	------	---	-------

Signed by John	1. 3/4	Date	10-20-93	<u> </u>
J.g. 104 0,				
Surveyor's Michigan License No.	16046			· 169
Surveyor's Michigan License No.	T0040	-	CORM ASSESSED TO B	V MICHIGAN STATE BOAR

Kalamazoo County Road Commission

REVISED MAY 14, 1975 BEVISED JAN., 1983