FEB 1 8 1994

COMMISSION

LAND CORNER RECORDATION CERTI Filing Requirement of Act 74, Mich. P.

FICATI	D	CLERK-REGISTER	Janu Ochung		33 NOV 4 PM 3 43	ECEIVED FOR RECORD	STATE OF BICHIGAN		
Д.	LIBE		ار مدد						
ne	giste	er or	Deed	0S &	tamp	& File	Numb	er 	
· · · · · -		A · B	С	D	E F	G H	1	K L M	
		 - -	-	} 5— 	_{-	3-		+1-1	
	. 4			8	_ 9 _	10-	11-	12	
oned	5 6	18		17	-16-	15-	14-	13	
the _and	7	\sqcup	_		.		+	1-1-	
nd 5 of a	6	 -19		! 20—	 21	22—	23-	24-	
ora das	9	┝	-			-	-	+ + -	
	, 1 0	—3 ⁰	:	29-	—2 ⁸	27-	26	25	
	11	-+	_			++	+	+	
	12	السا		J. 1	سأسا	1 4.	1 ./-	1 / 1	

For corners in

5. Private Claims

Kalamazoo Located In: Corner Code ## Schoolcraft Township T 4 S R11 W 1. Public Land Survey I-7 2. Property Controlling in Section 3. Miscellaneous T R Property in Sec.

, Recorded Plat

I John G. Kester , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentic in lines 1 and 2 above were in conformance with regulations and rules therefore as required in current manual of survey instructions of the United States Department of the Interior, Bureau of L Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 a. above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Court of Law; established, re-established, monumented, re-monumented, recovered, found expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: Corner Post established by U S Government Deputy Surveyor Robert Clark, 1826, Post in Mound in Prairie no accessories. Survey by Ed Strong, 1881, Found Stone, Accessories: Cherry 4 S48-10W 8412, Maple 7 S68W 11312. Remonumentation by F. Hodgeman,

1889, Found Stone & Brick of former survey and Bearing Trees all in place. Set Post (Solid Clay Tile with "X" on top) with Stone alongside.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner Post not recovered.

Remonumentation Corner set by F. Hodgeman not recovered. It appears that road construction may have removed all traces of the above corner evidence. Found Monument Box over Concrete Cylinder encasing ½" Iron Rod 3½' long.

> RATIFIED BY KALAMAZOO COUNTY REMONUMENTATION PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-7, Section Corner 14, 15, 22 & 23, T4S-R11W, Ratified by Kalamazoo County Remonumentation Program Peer Group on August 19, 1993. Found Concrete Cylinder encasing 1/2" Iron Rod 31/2! long and is accepted as the best available evidence of the position of the original corner. Removed Monument Box and Concrete encased Iron Rod. Placed 30" Harrison Monument in its place and placed Monument Box over Corner.

Set P.K. in P.P. N4	5E 73.55
---------------------	----------

Set P.K. in P.P. N30W 74.62

Set P.K. in P.P. N60W 80.80'

Set P.K. in P.P. S45W 42.87' 28" Maple \$71W 75.89'

Signed by _

Surveyor's Michigan License No. _

Kalamazoo County Road Commission