SURVEY & REMONUMENTATION

APR 27 1995

For corners in

COMMISSION

STATE OF MICHIGAN COUNTY OF KALAMAZOO RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 19704 DEC 14 PM 2 38

_K	(alamazoo		Located	ln:	Cor	ner Code ##		به پیس	د. مردو مد	di	-/	,		
P	Prairie Ronde Tow	nship						Henry	12 m	Jan .	7			
	Public Land Survey	•	т <u>4 S</u>	R 12 W		M-5	_	CLEF	K-RE	GIST	FR			
			τ	R	•		_	V 10 2.		.0,0,	-11			
			T	_ R			_		_					
	•		Τ	. R			_	LIBER	- 1	201	20	1		
2.	Property Controlling	s	T	R						ru.	AU.	L		
	in Section	s	T	R			_						•	
3.	Miscellaneous	s	T	. R		····	_	Register of i	Deeds !	Stamo	2 File	. Meer	nhai	
	Property in Sec.	s	T	. R			_ L	· · · · · · · · · · · · · · · · · · ·		Jeanip		, ITG		
	Lat Na	Doggedos	Diet											
	Lot No,							А В	C D	E F	G H	l J	K	L M
5.	Private Claims					·					ļ		Ĺĺ	
								3	T-i-	Τī	Ti	T	iΠ	
										11	11	1		
	Robert E. Snell			May	/ 17		94	⁴ [- !-	8-	- ∮-	10-		1-1	-12-
ا, _	hereby certify that under re							5	++	╂┷┼╌	╅╌┼╴	╌╂╾┤	┝╌╂	1.9
	lines 1 and 2 above were	•		_				6 18	17-	-16-	15		4—	13
	rrent manual of survey inst			_		,		7	4-4-	++	4-1-		\vdash	
	inagement or by a decree o				•			8 19	20		22-	,	<u></u>	_24_
	ove were in conformance w			_				e	1_1	ΙĪ.	ΙĪ	17	ĭΙ	Ī.
	ourt of Law; established,	re-establis	shed, monu	mented, re	-monument	ed, recovered	, found as	10 20	TT					
•	pressed below:				_	_		- -30-	- 29-	 -28 -	27-	 2	6-1	-25
NC	OTE: Not more than 4	-	III in the sa	ime town	and range,	may be reco	rded	11	1 	 	1	+	\vdash	_
	on this certificate	!.						12 -31-	32	33-	34-	3	5	36
								13						
Α.	Description of original	monume	ni and acc	essories a	na/or subs	equent resto	ration:							

- 1825: U.S. Government Survey; Set Post Corner to Sections 12 and 13 in prairie and raised mound.
- 1889: F. Hodgman, County Surveyor; Found stone and bearing trees of resurvey all in place. Set Post (3" Tile) (Done for Southwest Corner Section 7, T. 4 S., R. 11 W.)

NOTE: Prairie Ronde M-5 is Common Corner Schoolcraft A-5.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1994: Found 3/8" rod below pavement and top section of 3" tile broken and laying on it's side, below rod. Found second section of tile (2' in length) upright.

RATIFIED

BY KALAMAZOO COUNTY

REMONUMENTATION

PEER GROUP

7-21-94

C.	Descri	stion of monument for corner and accessories established to perpetuate locating the position of the corner:	
	M-5	Southeast Corner Section 12, T. 4 S., R. 12 W., Ratified by the Kalamazoo County Remo	m-
		umentation Program Peer Group on July 21, 1994. Found 3" round tile (2' Section) as	
		called for in 1889 remonumentation survey by F.Hodgman, and is accepted as a careful	and
		faithful perpetuation of the original corner's position. Placed 16" of 20" Harrison	
		monument with monument box over.	

PK	Nail	in	East	Side	34" Maple	North 33°	West	89.55
PK	Nail	in	East	Side	30" Maple	North 20°	West	141.54
PK	Nail	in	West	Side	Power Pole	North 15°	East	156.44
ĐΥ	Nail.	in	Was+	ahi2	Dower Pole	South 12°	Fact	102 183

NOTE: This corner is in common with A-5 Southwest Corner Section 7, T4S,R11W

LV	Nali	111	いたつじ	Side	LOMCI	LOIG	MUI LII	TO	Last	100.44
PK	Nai1	in	West	Side	Power	Pole	South	12°	East	102.18
CL	12th	St	reet		•		West			1.5
	_								-	

Date 12/14/94

Signed by John C. Snee	
Surveyor's Michigan License No. 9734	