SUBVEY & REMONUMENTATION

MAY 1 8 1998

LIBER 0 0 4 PAGE 0 1 1 7

SECTION		ORNER RECORDAT					
For corners in	r may r	Requirement of Act 74	, MRCN. P.A. 1	19/0			
Lake	Located in:	Ca-mar O = d = #			≅ 0	7	5
(County)	Located III.	Corner Code #			REGISTER OF DEEDS	FI REA	RECORDED LAKE COUNTY.
1. Public Land Survey	т ^{17N} թ 1	12W K-4	:		ISTER		O C
1. Fubiic Land Sulvey	1K T R				2 F	(LL)	
	TR			:	· 유 >	2	
0 D	TR				OF DEEDS	9 R	
2. Property Controlling 5 in Section 5	<u>`</u> R				8	త్	X
3. Miscellaneous	T R			i	-		•
Property in Sec.	S TR S TR						
			Ĺ,	Register	of Deeds	Stamp & Fi	le Number
4. Lot No, Recorded	Plat						
5. Private Claims			··	1 A B C	DEF	G H I	JKL
				2 - 6-	- - 4 -		-21-
Robert L. Wetherell	· Feb.	. 17. 98		3	+++	+++	
i, Robert L. Wetherell, in requirements of P.A. 74, Michigan P.	a field survey on	, 19 do heret	y state that under	r 4 - 7	-	10-	-1112-
conformance with regulations and rule:	s therefore as required in	the current meaust of eurosc	incimiations of the	. 5 - 1 - 1			-
United States Department of the Interior that the corner points mentioned in lin	or. Bureau of Land Mana	Idement or by a decree of a Co	surt of I am and for	ا ا ا ا	-17 16-	15-	-14 - 13-
Board of Land Surveyors or by a E	ecree of a Court of La	aw; established, re-establish	ed, monumented,	" 7			
recovered, found as expressed below:				8 -19	-2021-	22	-2324
NOTE: Not more than 2 corners,	all in the same town ar	nd range, may be recorded	; ;	9			 -
on this certificate.			ļ i	10 30	-2928-	27-	-26 - 25
				11			++-
				12 31	-3233-	- -3 4 -	-3536-
A. Description of original monum	ent and accessories :	and/or subsequent rectors	tion:	13			<u> </u>
K-4 - 1/4 Corner common to		·	•				
1838 - J. Hodgson, G.		974 - R. Griffin, LS 13		77 - R.L. Weth	erell. IS 2	4624	
#1 - 9" W. Oak \$52 ⁰ W	10 Links L	C.R.C L. 02, Pg. 20		rvey recorded		-	
#2 - 19" W. Oak N77 ⁰ E		eplaced Iron Pipe with		tnesses same a	s Griffin's		
Undated Co. Survey Re		" Square Concrete Monum		om 1974.			
Iron Pipe due East 46 of U.S.F.S. Post.		13 - 7" W. Oak N62 ⁰ W 44. 14 - P. Pole S38 ⁰ E 51.16					
•		5 - 7" Maple S44 ⁰ W 65.3					
3 Description of corner oxidence	#	6 - Post West 33.04'					•
Description of corner evidence	e lound and/or metho	a applied in restoring or re	eestablishing co	orner:			
K-4 - 1/4 Corner common to	Sections 11 & 12, T	17N, R12W, Yates Twp.,	Lake Co., Mi.				
			1				
I found Griffin's 5"	Concrete Monument i	n the centerline of a N	lorth and South	h gravel road.			
Condition of the acce	essories are as foll	ows: #1 Gone, #2 Gone,	#3 Found in g	good condition	, #4 Found	in good co	ndition,
#5 Found in good cond			·			•	
			RATIF	HED BY THE LAK	E CO. PEER	REVIEW GR	910
			; !	IN ACCORDA Cl	MAMMAN A	A. 345 Y. Υ. W.	
C. Description of monument for c	ninar and accepta	s satablished to managerate		!	DATE A	9.98	
. Description of monamon, lot o	omer and accessories	s established to perpetuat	e locating the p	osition of the co	rner:		
K-4 - 1/4 Corner common to	Sections 11 & 12, I	17N, R12W, Yates Twp.,	Lake Co., Mi.				
		<u> </u>	:				
		nt as a substantial mar	i	orner, and is	accepted as	a careful	and
таттитиц re-establish	ment of the positio	n of the original corne	er.				<i>;</i>
10" W. Oak N59 ⁰ W 44.5	9' (dock spike in S	. side) #3	1			<u> موجودين</u>	·
P. Pole \$39 ⁰ E 51.14'						OF M	CHICAN
10" Maple S50 ⁰ W 65.17 10" R. Oak S72 ⁰ E 94.0					A ST	A. L. Comment	
			,			ROBERT	L.
signed by Salut	1. Wet	hired	Date \frac{\frac{1}{2}}	14.98		WETHER	illes
Surveyor's Michigan License No.	24624			1	i	CLEVE	YOR Im