LAKE COUL

FEB 1 8 1994

LAKE COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

DEC	13	3	43	PH	'93

For corners in	Filing Requiren	nent of Act 74, Mich. P.A	. 1970	Sucinda	- M. Wocho	ut
	ated In:	Corner Code ##		RECISTER		
1. Public Land Survey	7 N R 13 W	к-13				
2. Property Controlling S T in Section S T 3. Miscellaneous S T S T	R		Register of	Deeds Stamp (& File Num	ber
	R					
4. Lot No, Recorded Plat _ 5. Private Claims			A B	CDEF	G H I J	КЬМ
Robert L. Wetherell , in a field sundo hereby certify that under requirements of P.A in lines 1 and 2 above were in conformance vourrent manual of survey instructions of the Ur Management or by a decree of a Court of Law an above were in conformance with the rules of the Court of Law; established, re-established, expressed below: NOTE: Not more than 4 corners, all in the on this certificate. A. Description of original monument and K-13 - (Section corner common to Sec	a. 74, Michigan P.A. of vith regulations and a nited States Department of the corner per Michigan Board of Lamonumented. re-mones are same town and	rules therefore as required in the first of the Interior, Bureau of La coints mentioned in lines 3, 4 and and Surveyors or by a Decree of numented, recovered, found range, may be recorded	ned 6 18- the 7		-10 -11 -15 -14 -14 -15 -14 -15 -14 -15 -14 -15 -14 -15 -14 -15 -15 -15 -15 -15 -15 -15 -15 -15 -15	12
1838 ~ John Mullett, D.S., G.		ilton Nye, Re-survey		West, Surveyor		
#1 18" W. Pine N36-1/2 ^O W 46 L	inks #2 4" S.	Pine \$10 ⁰ W 106 Links Pine \$56 ⁰ E 100 Links	#4 12" B. Oak	N55-1/4 ⁰ W 251 71 ⁰ E 255 Links	_	

(SEE OVER FOR CONTINUATION OF "A" - LAND CORNER RECORDATION CERTIFICATE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-13 - (Section corner common to Sections 35 and 36, T17N, R13W, on the county Line)

> I found 1-1/4" Iron Pipe that was previously used by George Blass and Robert Griffin. Condition of accessories are: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Gone, #6 Gone, #7 Found in good condition, #8 Found in good condition, #9 Found in good condition, #10 Found in good condition, #11 Found in good condition, #12 Found in good condition, #13 Gone, #14 Gone, #15 Found in good condition, #16 Found in good condition, #17 Gone.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-13 - (Section corner common to Sections 35 and 36, T17N, R13W, on the county Line)

> Replaced 1-1/4" Iron Pipe with 3/4" x 24" Re-rod with Lake County Brass Cap and is accepted as a faithful and careful re-establishment of the position of the original corner.

8" Tw. W. Oak S55 $^{\rm O}E$ 50.07' (60d nail in SW side of tree) N40^OW 84.77' (60d nail in NE side of tree) (#7) 24" B. Oak 16" B. Oak \$57°W 60.90' (60d nail in NW side of tree) (#8) 20" W. Oak N1904 69.10' (60d nail in NE side of tree) N45^OE 46.95' Tag 8/70 USFS Post

Signed by Signed Surveyor's Michigan License No. __ Date _

SE OF MICHIGAN ROSERT L WETHERELL SURVEYOR NO

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, PRUSEO MAY 14 REVISED MAY 14, 1975

Approved by Peer Review Group December 6, 1993 2. W. Robert L. Wetherell, County Representative

REVISED JAN., 1983

LIBERO 03 PADE 02 12 A

CONTINUATION OF "A" - LAND CORNER RECORDATION CERTIFICATE

1936 - W.H. Welton, USFS Technican #14 Standard Post N50°E 0.44 Chains

1942- George Blass, LS 5489 Found 1-1/4" Iron Pipe #6 14" Oak S55°E 60.40' #7 18" B. Oak N40°W 84.30' #8 10" B. Oak S57°W 60.70'

1969 - Robert Griffin, LS 13584 Found 1-1/4" Pipe # 9 Power Pole N40°E 78.85' #10 16" B. Oak S15°E 94.00' #11 10" B. Oak S57°W 60.70' #12 18" B. Oak N40°W 84.30' #13 Tele. Pole S45°E 43.32'

UNDATED G.H. JOHNSON, COUNTY SURVEYOR
2 Irons - Well point and 1" Pipe
#15 12" B. Oak NW 84.3'
#16 6" B. Oak SW 60.8'
#17 8" B. Oak SE 60.4'