

JAN 2 5 2001

## LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For corners in Lake		Located in: Corner Code#					LA	RE KE (	COR	DED VTY.	<b>ŢĦŶĬ</b> Ķ E
1. Public Land Survey	,	T 19 N	R 13 W	<u>B-11</u>		LIBER	00	4 1	AGE ()	27	6
		<u>T</u>	<u>R</u>				Dec	8	]];	21	#c*() <b>0</b>
		<u>T</u>	R							1.	The s
		<u>T</u>	R				D C	OLCT OLCT		Z	For
2. Property Controlling in Section	, <u>s</u>	т	R				ne.	0121	EK ()	r De	E64s
	s	<u> </u>			Registe	or of F	ehaa(	Stam	n & F	ile Nı	ımber
3. Miscellaneous Property in Sec.	s	т	R	l	. registe	. Of L	~~~	- J.C.	.p w 1		
	<u>s</u>		R	<u> </u>							
<ol> <li>Lot NoReco</li> <li>Private Claims</li> </ol>	rded Pla	nt			1						LM
, Robert L. Wetherell, in	a field su	rvey on Fe	bruary 23.	2000, do	3	7		9	3 10	11	12
nereby certify that under repoints mentioned in lines	1 and 2 a	bove were in	conformance w	ith regulations and	5			<del></del>			
ules therefore as required States Department of the	d in the c Interior l	urrent manual Bureau of Lan	l of survey instru d Management	ctions of the United or by decree of a	6 7	18	17	16	15	14	13
Court of Law and/or that	the come	r points ment	ioned in lines 3,	4, and 5 above were	8	19	20	21	22	23	24
n conformance with the r Of a Court of Law; establi	ules of th shed, re-	e Michigan Bo established, n	oard of Land Su nonumented, re-	rveyors or by a Decree -monumented,	9 10	30	29	28	27	26	25
ecovered, found as expre			·		11	31	32	33	34	35	36
					12 13	31	عد	່ານ	J#	သ	30

Description of original monument and accessories and/or subsequent restoration:

1838 - S. Sibley, G.L.O. #1 - 8" Pine N57°W 14 Links

#2 - 8" Pine S39°E 17 Links

1986 - K. Ross, LS 17634

#5 - 5" R. Pine N40°E 73.56'

Survey recorded Liber 03, Pg. 42 (Set 5" Concrete Monument) Set corner on line between the N.E. corner and N.W. corner at prorated G.L.O. #3 - 11" W. Oak S88°W 121.62' #4 - 11" B. Oak S8°E 21.08'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found the 5" Square Concrete Monument set by Ross.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found in good condition, #4 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the 5" Square Concrete Monument as a substantial marker for the corner, and is accepted as a careful and THERIE faithful reestablishment of the position of the original corner.

10" W. Oak N88°W 121.53' (60d spike in N. side) #3 12" B. Oak S05°E 21.06' (60d spike in E. side) #4 7" R. Pine N44°E 73.57' (60d spike in E. side) #5 8" R. Pine N36°W 67.02' (60d spike in N.E. side)

MO CO, FEER REVIEW GROUP LOCATE WITH P.A. 345 CHAIRMAN RUW HATIFIED BY THE LAND IN ACCORDA DATE 12-5-2000

Signed by

Wetherell

Date December 6, 2000

Surveyor's Michigan License No. 24624

CARR FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 2843971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999

ROSERTI

METHEBELL

LAND

SURVEYOR

NO. 24624