SUNVEY & REMONUMENTATION

MAY 1 8 1998

Surveyor's Michigan License No.__

LIBER 004 PAGE 0120

For corners in Lake Filing Require	R RECORDATION CERTIFICA ement of Act 74, Mich. P.A. 197	ATE 70	REGISTER OF DEEDS	APR I	RI LAKE
Located In; Corn	er Code #		Sucinda GISTER	•	COO
1. Public Land Survey T 19N R 14W	c-2		R OF	್ ಕ	ECORDE
<u> </u>			: DEED		78
!R TR			E S		- 5
2. Property Controlling S TR			es C	25	·
in Section STR 3. Miscellaneous STR					
Property in Sec. STR_					
		Registe	r of Deeds S	tamp & F	ile Number
4 i of No Recorded Plat					
4. Lot No, Recorded Plat 5. Private Claims		ABC	DEF	G H I	ЈК L M
		2 6-6	_ 5 4 _	1	
		3			
I. Robert L. Wetherell , in a field survey on	98 do hereby state that under	4	_89_		
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mer conformance with regulations and rules therefore as required in the curre	tioned in lines 1 and 2 shove were in	5			
United States Department of the Interior, Bureau of Land Management of	Thy a decree of a Court of Law and for	6 18	-12		14 13
that the corner points mentioned in lines 3, 4 and 5 above were in confo Board of Land Surveyors or by a Decree of a Court of Law, estat	rmance with the rules of the Michigan	7 10			
recovered, found as expressed below:	maned, re-established, monthheated,	8 19	_2021_	22	23 24
NOTE: Not more than 2 corners, all in the same town and range	may be recorded	9		1	
on this certificate.	, may be recorded	10-30-	-2928-	27	_2625
		11		1-1-1	
		12 31	_3233_	34	35 36
		13			
 Description of original monument and accessories and/or s 	ubsequent restoration:				
C-2 - 1/4 Corner common to Sections 5 & 6, T19N, R14W	, Sauble Twp., Lake Co., Mi.				
1838 - S. Sibley, G.L.O.	1908 - J.W. Nichoson, Co.	Sur.			
8" Cedar for corner	"Found no cedar corner tr	"Found no cedar corner tree after diligent search. Set post			
2640' to Southwest corner	at edge of swamp on true				,
2870.34' to Northwest corner #1 - 22" Pine Stump S5 ^o E 60 Links Showed distance of 40 Chains (2640') to Southwe				ct for a	onnon and
	43.08 Chains (2843.28') t				office and
B. Description of corner evidence found and/or method applie	ed in restoring or reestablishing corne	er:			
C-2 - 1/4 Corner common to Sections 5 & 6, T19N, R14W	, Sauble Twp., Lake Co., Mi.				
				-	
This corner falls in a swampy area that is very was unable to recover Nichoson's post or access proration of Nichoson's distances.					
	DATICION	BY THE LAKE	CO, PEER R	EVIEW GR	OUP
I measured a total distance of 5589.69'	HATIFIED		NCE WITH P.A.		
2691.23 feet to Southwest corner of Section 5, 2898.46 feet to Northwest corner of Section 5	•	ÇP	DATE 4.9	-98	
	ahad ta magaataata faasiin - tira			, ,	
C. Description of monument for corner and accessories establi		tion of the c	orner:		
C-2 - 1/4 Corner common to Sections 5 & 6, T19N, R14W	, sauble twb., take co., mt.				
I set a 1-1/4" Iron Rod 3 feet long with 8" Ced re-establishment of the position of the origina		oted as a ca	ereful and f	aithful	
7" Maple N34 ⁰ W 42.01' (60d spike in W. side)			_	ACTES DE	A SALL
2" White Pine S80°W 25.2' (Center of Tree)			A STATE OF THE STA	GTATE (FINE
5" Cedar \$23 ⁰ W 28.20' (60d spike in E. side)			and the second	ROA	164
7" Cedar \$13 ⁰ E 7.50' (60d spike in E. side)			1	WETIS	外人
D. 4 1.1	.1 .	1 0-	7	SILAN	DEL 1
Signed by Robert J. Ukther	pate 4.14	+-48	· / *	-MINE!	00 1

24624