DEC 1 4 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For corners in Lake		Located in:	Corner Code#				L				, MI. Page (0237	
1.	Public Land Survey		T_20N	<u>R</u> 12W	<u>I-12</u>			DE	c 9	9	59	M'S	19
			<u>T</u>	R		Sherry myers							
			<u>T</u>	R		REGISTER OF DEEDS							
			Т	R		REGISTER OF DEEDS							
2.	Property Controlling s in Section			R									
	in Section	s	т	R		.			. .				
3.	Miscellaneous	S	<u>T</u>	R		Registe	er of I	Deeds	Stan	np & I	File N	umbei	r
	Property in Sec.	s	<u>T</u> _	R									
	Lot No Reco	orded	Plat				4 в е	C D I	E F (; н .	IJķ	LM	
5.	Private Claims					1	Γ	I	Γ				
i, <u>F</u>	obert L. Wetherell, in a	field su	rvey on <u>Octobe</u>	r 7	1999, do	2 3	6	5	4	3	2	1	
nere	eby certify that under receits mentioned in lines 1	quireme and 2 a	ents of P.A. 74, N	lichigan P.A. o	f 1970, the corner	4	7	8	9	10	11	12	
rule	s therefore as required i	n the c	urrent manual of	survey instruct	ions of the United	5 6	18	17	16	15	14	13	
Cou	es Department of the In rt of Law and/or that the	e corne	r points mention	ed in lines 3, 4,	and 5 above were	7 8	19	20	21	22	23	24	
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							30	29	28	27	26	25	
1000	vereu, round as expres	sea per	UVV.			11 12 13	31	32	33	34 (35	36	
<u>I-12</u>	- ¼ Corner common to	o Sectio	ons 34 & 35, T20	0N, R12W, La	ıke Co., Mi.	13				'			

A. Description of original monument and accessories and/or subsequent restoration:

1838 - S. Sibley, G.L.O. "6" - Beech for 1/4 Corner."

No record of corner since original survey.

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

1 set the corner in line with fence to the East and on line between Section corners. Corner is 2 feet more or less East of centerline of road. I measured: 2623.12 feet North to Section corner and 2619.34 feet South to Section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3/4" x 24" re-bar with Lake County Remon Cap, and is accepted as a careful and faithful perpetuation of the position of the original corner.

18" Maple N8°W 104.71' (60d spike in W. side)

18" Elm N37°E 46.04' (60d spike in N.W. side)

18" Maple \$16°W 132.61' (60d spike in E. side)

8" Willow S37°W 80.60' (60d spike in S.E. side)

PATIFIED BY THE LAKE CO. FERR REVIEW GROUP
IN ACCOMDANCE VITH P.A. 845
CHARRAIN L. J. W.
DAYE 10-19-40

RECORDED

Robert L. Wetnull Date 10/22/99

Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF

REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999