SURVIVE REMONUM

MAY 1 6 BS7

产统州和加州人。1111年11日

For	r corners in Lake	•	CORNER RECORDATION CERTIFICATE Requirement of Act 74, Mich. P.A. 1970			REG	SEP 12	LAKE	
	(County)	Located In:	Corner Code	e <i>#</i> #		REGISTER		99	
1.	Public Land Survey	T 20N R 121 T R R T R T R T R T R T T R R T R T T R T R T T R T R T T R T			<i>325</i> 9 .87.5	R OF DEEDS	3 12 PN 196	RDED MI.	
2.	Property Controlling in Section	S T R S T R	<u></u>		, , , ,				
3.	Miscellaneous Property in Sec.	S T R			egister of De	eds Stamp	& File N	lumber	
		Recorded Plat			— авс	DEF	G H 1	JKLI	
5.	Private Claims				2 6	5-4	3		
	Robert L. Wetherell	_ , in a field survey on	August 23,	96	3 4 7 5	89	10-	1112	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					6 _18_	-1716	15	_1413	
Mar abo Cou	nagement or by a decree o	f a Court of Law and/or that the c vith the rules of the Michigan Bo re-established, monumented,	orner points mentioned ard of Land Surveyors o	in lines 3, 4 and 5 r by a Decree of a	8 19 9	29 28	22	23 24	
10.	TE: Not more than 4 on this certificate	corners, all in the same tow	n and range, may be	recorded	11	-3233			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-13 - South 1/4 corner of Section 35, T20N, R12W, North Newkirk Twp., Lake Co., Mi.

Description of original monument and accessories and/or subsequent restoration: J-13 - South 1/4 corner of Section 35, T20N, R12W, North Newkirk Twp., Lake Co., Mi.

I found metal strap iron with stones, earthenware and broken glass around it 6 feet more or less South of centerline of East and West dirt road. This position fits East 1/16 line fence running North.

I measured the following distances:

1839 - S. Sibley, G.L.O. #1 - 8" B. Ash N43°W 20 Links #2 - 10" Birch N27°E 8 Links

To Southwest corner of Section 35 - 2652.02 feet

To Southeast corner of Section 35 - 2676.42 feet

I did not recover accessories No. 1 or No. 2.

HATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH PA. 345 CHAIRMAN (J. X. W.).

DATE 8-27-96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-13 - South 1/4 corner of Section 35, T20N, R12W, North Newkirk Twp., Lake Co., Mi.

I set a 3/4" x 24" re-bar with a Lake County Brass cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. CATE OF MICHIGA

13" Cedar S44^OE 32.40' (60d spike in N.E. side)

10" Cedar N48°E 54.39' (60d spike in E. side)

8" Cedar \$15°W 17.77' (60d spike in E. side)

11" Cedar N65°W 88.34' (60d spike in N. side)

September 6, 1996

Signed by .

Surveyor's Michigan License No. _

L. Wetherell Date

24624

ROBERT L

WETHERELL

LAND SURVEYOR

NO.

FORM APPROVED BY MICHIGAN STATE BOARD