

LIBEROO3 PAGE 0277

	Lake (County)	Located In:	Corner Code ##	
	(County)	20N 13W	E-8	el
1.	Public Land Survey	T R		TE OF MICHIGAN \ RECORDED /4 DAY OF
	•	T R	• • • • • • • • • • • • • • • • • • •	UNTY OF LAKE PROPERTY AD, 81
	•	T R		O'Clock 11. 30AM
	· .	T R		HEGISTER OF DEEDS
2.	Property Controlling	S T R		, <u>,                                  </u>
	in Section	S T R		
3.	Miscellaneous	S T R		egister of Deeds Stamp & File Number
		\$ T R		ogister of Decas oranip a tire Ramber
4.	Lot No, Rec	orded Plat		— A B C D E F G H I J K L
5.				
				2 - 6 5 4 3 2 1
				3
	Robert L. Wetherell		October 27, 94	4 7 8 9 10 11 11
				5
			P.A. of 1970, the corner points mentioned	6 -18 -17 -16 -15 -13 -141
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				7
				21 7 22 7 2
expressed below:			10 30 29 28 27 26 2	
NO	TE: Not more than 4 corn	ers, all in the same tow	n and range, may be recorded	11
on this certificate.			12 31 32 33 34 35 3	
				13
A.	Description of original mo	nument and accessories	and/or subsequent restoration:	
	E-8 - 1/4 Corner common t	o Sections 20 and 21, T2	<u> 20N, R13W, Eden Township, Lake Co., M</u>	<u>i.</u>
	<u> 1839 - John Brink, G.L.O.</u>		1983 - Robert L. Wetherell, LS 2462	1989 - Sammy Barnett, LS 16923
	#1 - 6" Maple N21 <sup>0</sup> E	28 Links	Found 1/4" x 4" x 24" Flat Iron and	Replaced Flat Iron with
	#2 - 8" Maple \$48 <sup>0</sup> W	14 Links	accessories #3 and #4.	5" x 60" U.S.F.S. Concrete Mon.
			#5 - 5" R. Oak N41 <sup>0</sup> E 45.77'	# 9 - 10" R. Pine S33 <sup>0</sup> E 65.55'(#6)
	1920-1930 - George	Johnson, Lake Co. Sur.	#6 - 10 <sup>n</sup> R. Pine \$33 <sup>0</sup> E 65.551	#10 - 5" R. Oak N76 V 39.31' (#8)
	Iron For Corner	-	#7 - 5" W. Oak S52 <sup>0</sup> W 47.09'	#11 - 7" R. Oak N41 <sup>0</sup> E 45.77' (#5)
	#3 - 10" B. Oak N75	<sup>о</sup> Е 23'	#8 - 5" R. Oak N76 <sup>0</sup> W 39.31'	L.C.R.C. Liber 003, Page 093.
	#4 - 8" W. Oak \$25		L.C.R.C. Liber 003, Page 002.	
В.	Description of corner evid	ence found and/or meth	od applied in restoring or reestablishin	ng corner:

E-8 - 1/4 Corner common to Sections 20 and 21, T20N, R13W, Eden Township, Lake Co., Mi.

found U.S.F.S. 5" x 60" Concrete Monument. Condition of the accessories is as follows: #1 Gone, #2 Gone, #3 Found in good condition, #4 Found in good condition, #5 Found in good condition, #6 Found in good condition, #7 Found in good condition, #10 Found in good condition, #11 Found in good condition.

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345 CHAIRMAN G. Z.W. DATE 11/6/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E-8 - 1/4 Corner common to Sections 20 and 21, T20N, R13W, Eden Township, Lake Co., Mi.

I accepted the U.S.F.S.  $5" \times 60"$  Concrete Monument as a substantial monument for the corner, and is accepted as a careful and faithful re-establishment of the position of the original corner.

7" R. Oak N41<sup>O</sup>E 45.57' (Dock Spike in N.W. side of tree) (#5 & #11)

7" R. Oak N71°N 39.25' (Dock Spike in S. side of tree) (#8 & #10

11" R. Pine S33°E 65.10' (Dock Spike in E. side of tree) (#6 & #9)

16" R. Oak S90E 34.71' (60d spike in E. side of tree)

14" B. Oak N73°E 22.72' (60d spike in S. side of tree) (#3)

Signed by Jabut J. Wether Date
Surveyor's Michigan License No.

11/9/94

ROBERT L.
WETHERELL
LAND
SURVEYOR
NO.
24624

FORM APPROVED BY MICHIGAN STATE BOARD OF TANDASURVE FOR JAN.

REVISED JAN., 1983