FEE 2 3 1800

LAND CORNER RECORDATION CERTIFICATE LIBER 004 PAGE 0 173 CESTON Filing Requirement of Act 74, Mich. P.A. 1970 For corners in REGISTER OF DEEDS Lake Located in: Corner Code # (County) 20N 14W H-13 1. Public Land Survey T т 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. __, Recorded Plat 5. Private Claims 1 2 Robert L. Wetherell Oct. 8 98 3 in a field survey on 19 do hereby state that under 4 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 5 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 7 Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented. recovered, found as expressed below; NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 10 A. Description of original monument and accessories and/or subsequent restoration; H-13 - South 1/4 Corner Sec. 34, T20N, R14W, Lake Co., Mi. 1837 - J. Mullett - G.L.O. 1953 - G. Blass, LS 5489 1980 - C. Cole, LS 17615 #1 - 16" W. Oak N25°E 30 Links "Set 3/4" x 24" Pipe from Developed plat of #2 - 8" W. Oak N160W 25 Links Mitchell's pine stump witness". "Heritage Bay" #4 - 12" W. Oak N58⁰E 74.25' 1905 - J. Mitchell, U.S. Deputy Sur. No witnesses given. "Identified old witness trees and stake. #5 - 14" R. Pine N43^OW 95.75' #3 - 30" Pine Stump N23^O30'W 33.0' Planted 4" x 4" x 4' Maple stake. This post located RATIFIED BY THE LAKE CO. PEER REVIEW GROUP
IN ACCORDANCE WITH P.A. 345
IN CHAIRMAN R. L. W. in marshy ground near a point of land to the North". #3 - 30" Pine Stump N23⁰30'W 50 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: DATE 10. 27-98 H-13 - South 1/4 Corner Sec. 34, T2ON, R14W, Lake Co., Mi. I found 3/4" pipe in centerline of East and West blacktop road. The 3/4" pipe fits well with monumentation in the plat of "Heritage Bay". Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-13 - South 1/4 Corner Sec. 34, T20N, R14W, Lake Co., Mi.

I replaced the 3/4" pipe with a 3/4" x 24" rebar with Lake County Brass Cap, and is accepted as a careful and faithful perpetuation of the position of the original corner.

17" R. Pine N41^OW 96.35' (60d spike in S.W. side) #5

12" R. Oak N58°W 158.75' (60d spike in N.E. side)

18" W. Oak N62°E 125.10' (60d spike in N. side)

22" R. Oak N42°E 159.13' (60d spike in S.E. side)

3/4" x 24" rerod with Brass Cap (N.1/4 Sec. 3, T19N, R14W) - East ~ 623.57'

Signed by Kobert atherell 24624

Surveyor's Michigan License No._

Date

of Bienics ROBERT WETHERELL LAND SURVEYOR NO 24624 TO LATE

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY