REMONUMENTATION

	SECTION		RNER RECORDATION		0	RECEIVED	FOR RECORD
Fore	corners in			1	ı	(LULIPED	I ON WECOUR
<u>La</u>	peer (County)	Located In: Metamora Township	Corner Code#			98 DEC 2:	2 PM 3:33
1. F	ublic Land Survey	T6N R10F T R T R				Meliese REGISTE LAFRE	Da Vaugh
ii 3. N	Property Controlling 1 Section Miscellaneous Property in Sec.	S T R S T R S T R S T R			(18) Regis	iter of Deeds	Stamp & File Number -
4. L 5. F	ot No, Record	ed Plat			A B C		G H I J K L M
required that Boareco	iuston K. Kennedy in irements of P.A. 74, Michigan Pormance with regulations and rule ded States Department of the Interest or or points mentioned in irred of Land Surveyors or by a vered, found as expressed below.	P.A. of 1970, the corner points es therefore as required in the rior, Bureau of Land Managernes 3, 4 and 5 above were in Concerce of a Court of Law; v.	e mentioned in lines 1 and 2 current manual of survey instrem to by a decree of a Court conformance with the rules of established, re-established,	above were in ructions of the of Law and/or f the Michigan	2 6 3 4 7 5 6 18 7 8 19 9	-17 -16	10 - 11 - 12 - 13 - 13 - 22 - 23 - 24 - 1
NO	TE: Not more than 2 corner on this certificate.	s, all in the same town and	d range, may be recorded		10 30 11 12 31 13	32 33	34 35 36
A.	Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post 13" White Oak N09°E 97 Links; 11" Black Oak S50°W 46 Links 1.) 1972-Henderson, PS #16043; LCRC L.1, Pg.457 – Fnd a ½" Iron Pipe 2.) 1972-Kay, PS #14096; Survey L.001, Pg.422 – Object found not stated, used the same wit as 1972 LCRC 3.) 1972-Henderson, PS #16043 Survey L.1, pgs 572 & 573 – Fnd ½" Pipe, used same wit as 1972 LCRC 4.) 1975-Elrich, PS #18986; Survey L.3, Pg.315 – Fnd ½" Iron 5.) 1994-Kennedy, PS #17623; Unrecorded Survey – Fnd ½" Iron Rod 6.) 1996-Kennedy, PS #17623; Unrecorded LCRC for M-5 Hadley Township – Fnd a 5/8" Square Iron Rod						
₿.	1998-Kennedy Surveying, Inc. – Kennedy, PS #17623 - Fnd a ½" Iron Rod located in the existing centerline of Baldwin Road extending to the North & South, which has a gravel surface, also 5 feet North of the existing centerline of Caley Road extending to the East, which has gravel surface. The corner as recovered is on the range line. Corner common to Sections 12 & 13, T6N, R9E, Hadley Township (M-5) is located 80.31 feet to the North.						
Witnesses from LCRC #1, Surveys # 4 & 5 were used to recover and verify the location of the found ½" Iron Roll accepted the found ½" Iron Rod as the best evidence of the original corner positon.							FOR MICHIGANIA
	Field measurements s	see back side of LCRC					HUSTON KENNEDY
C.	Description of monument A-5 I replaced the found Remonumentation, PS N21°E 111.42' Set Mag N73°W 81.02' Set Mag S27°W 128.88' Set Mag S19°E 257.92' Set Mag North 80.31 feet, corne	d ½" Iron Rod with a 1/ #17623 J Nail & Remon Washe Nail & Remon Washe J Nail & Remon Washe J Nail & Remon Washe	/2" x 24" Iron Rod w/2" er NW face Power Pole r South face 16" Oak er SE face 24" Poplar er East face 8" Oak	diameter bra	ass cap stan	the damer in the damer is a second to the damer in the da	SURVEYOR / _ =
	ne selected location is an e position of the original		generally accepted by				t available evidence of
	gned by:	No 17	673	Date	-28-9	75	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYOR'S, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995



FIELD MEASURMENTS BETWEEN

A-5 to A-4

No GLO Survey recorded in Liber 1, page 572 = 2651.85 Ft. 2651.42 Ft. (MEA 1998)

A-5 to A-6

No GLO Survey recorded in Liber 001, page 422 = 2650.54 Ft. Unrecorded Survey by Kennedy, PS #17623 = 2648.25 Ft. 2648.16 Ft. (MEA 1998)

A-5 to M-5

I.2 O GLO = chains or 79.20 Ft. Survey recorded in Liber 3, page 315 = 78.22 Ft. 80.13 Ft. (MEA 1998)

> PEER GROUP APPROVED LAND CORNER PA245 OF 1990

> > P.S. CO. SURVEYOR

615C (t

PEHLC REHONT 9.00 F0075 2.00