

MAR 1 3 1998

SECTION

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECE	IVED	FOR	RECOR	C

97 AUG 11 PM 2: 29 For corners in Lapeer Corner Code # Located In: Metamora Township Melisme De Vaugh REGISTER OF 6N R D-5 1. Public Land Survey R R 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims Huston K. Kennedy , 19 <u>97</u> do hereby state that under 6/27in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

- A. Description of original monument and accessories and/or subsequent restoration: 1822-GLO Wampler, D.S., Set Post 6" Ash S62"W 21 Links; 6" Lynn N06°E 17 Links
 - 1.) 1979-Kay, PS #14096; Survey L.5, Pg.231 Fnd ?

recovered, found as expressed below:

- 2.) 1988-Elrich, PS #18986; Unrecorded Survey Fnd ?
- 3.) 1990-Kennedy, PS #17623; Unrecorded Survey Fnd 1" Iron Rod in a Monument Box
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 1996 Kennedy Surveying, Inc. Kennedy, PS #17623 Fnd 1 Iron Rod in a Honument Box in the existing centerline of Lapeer Road (M-24) Highway) extending to the North & South, which has a bituminous surface over a concrete base. Also the existing centerline of Caley Road extending to the West, which has a gravel surface.

Witnesses from Unrecorded Survey #3 were used to recover and verify the location of the found 1" Iron Rod in a Monument Box.

I accepted the found 1" Iron Rod in a Monument Box as the best evidence of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5 I replaced the found 1" Iron Rod with a 1/2" x 18" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation #17623 in a existing Monument Box

N86°W 93.42' Set PK & Remon Washer Top of Guard Rail Post

S73°W 93.08' Set PK & Remon Washer Top of Guard Rail Post

S87°E 23.84' Set PK & Remon Washer Top of Guard Rail Post

S47°W 52.30' Set PK & Remon Washer NW face Light Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best position of the original corner.

Signed by Surveyor's Michigan License No Date

8

10 11

A COUNTY COUNTY

REVISED OCT. 1995

Petersimmitteen (%)

LIBER 0005 PAGE 0422

FIELD MEASUREMENTS BETWEEN

D-5 to D-4 No GLO, 2668.45 Ft. (MEA 1996), 2668.64 Ft. (MEA 1996) D-5 to D-6 No GLO, 2618.15 Ft. (MEA 1996)

> PEER GROUP APPROVED LAND CORNER PA 345 OF 1990 APEER COUNTY

DATE 8-27-96

MISC D 9.80 REMLC POO75 REMONT 2.00