BUNVEY & REMONUMENTATION

MAY 28 1997

RECEIVED FOR RECORD

COMMISSIONAND CORNER RECORDATION CERTIFICATE

96 DEC 27 PH 1: 11

af the

ROFESSIONAL MANAGEMENT OF THE STREET

July 17, 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Filing Requirement of Act	74, Mi ch. P.A. 1970	
For corners in LAPEER Located In:Metamora Twp. Corner (Code #	Malissa Da Vauch
(County)	3000 #	REGISTER OF BEEDS LAPER OF DECISION
	,	CAPERS MITT MERICHIGAN
	- 5	·
T R	THAT THE TAX TO THE TA	•
TR		
2. Property Controlling S T R	···	
in Continu		
3 . Miscellaneous S T R Property in Section S T R		1
Property in Section S T R	Regis	ter of Deeds Stamp & File Number
4 Let No. Reported Plat		* .
4. Lot No, Recorded Plat 5. Private Claims		ABCDEFGHIJKE
V. 111440 O.C.111		2 6 3 2
•		3
•		4 - 7 - 8 - 9 - 10 - 11 - 12 -
I, Histon K. Kennedy in a field survey on June 3	, 19 <u>96</u>	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the coin lines 1 and 2 above were in conformance with regulations and rules therefore as it	mer points mentioned	6 18 17 16 15 14 13
manual of survey instructions of the United States Department of the Interior		7
Management or by a decree of a Court of Law and/or that the corner points mention		8 19 20 21 22 23 24
5 above were in conformance with the rules of the Michigan Board of Profession Decree of a Court of Law; established, re-established, monumented, re-monument		9
as expressed below:	100, 100, 100, 100, 100, 100, 100, 100,	10 30 23 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be	recorded	11
on this certificate.		12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subseque	ent restoration:	13
1817-GLO Joseph Wampler, D.S.; Set Post; 14" White Oak N78°E 53 Link		PEER GROUP
1.) 1977-Henderson, PS #16043; LCRC, L.3, Pg.342 - Set 1/2" Iron		APPROVED LAND CORNER
2.) 1972-Henderson, PS #16043; Survey, L.1, Pg.352 - Fnd P.K. Nail,	No witnesses	PA 345 QF 1990
3.) 1977-Henderson, PS #16043; Survey, L.4, Pg.297 - Fnd P.K. Nail, used same with as first LCRC 4.) 1982-Elrich, PS #18986; Survey, L.6, Pg.271 - Fnd 1/2" Iron		
5.) 1977-Elrich, PS #18986; Unrecorded Survey - Fnd ?	_	pay D_
6.) 1987-Elrich, PS #18986; Unrecorded Survey - Fnd 1/2" Iron Rod	ţ	RAY DAVISO.S. CO. SURVEYOR
7.) 1953-Lapeer County Road Commission Unrecorded Witnesses - Fnd 3/		DATE 7-16-96
B_Description of corner evidence found and/or method applied in rest 1996-kennedy Survey, Inc Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod extending East & West, which has a bituminous surface with a fer driveway to house #2250.	oring or reestablishing co w/cap at the surface in nce-tree line extending t	orner: the existing centerline of Dryden Road to the North & South and 13 feet East of
Witnesses from LCRC #1 & Survey #4 were used to recover and ver		· -
I accepted the found 1/2" Iron Rod w/cap as the best evidence o	f the original corner po	sition.
FIELD MEASUREMENTS BETWEEN I-5 to J-5 GLO = 40.42 chains or 2667.72 Ft.	7.F. to 11.F. 01.0	
I-5 to J-5 2708.57 Ft., L.4, Pg.297	J-5 to K-5 GLO = 40.42	Chains or 2667.72 Ft. Lapeer County Road Commission
I-5 to J-5 2708.54 Ft. Unrecorded Survey by Elrich PS #18986	J-5 to K-5 2628.44 Ft.	Unrecorded Survey by Elrich PS #18986
I-5 to J-5 2708.35 Ft. (MEA)		(to 1/2" Iron Rod)
I-5 to J-5 2710.78 Ft. Lapeer County Road Commission	J-5 to K-5 2634.76 Ft. N 527562.5160 E 1342113	81 1460
C. Description of monument for corner and accessories established to J-5 I replaced the found 1/2" Iron Rod w/cap with a 1/2" x 24" Iron Rod	perperuate locating the p	outsition of the corner:
J-5 in a new Monument Box	u w/2 Ulametel Drass Cal	
SO3°W 34.63' Set PK & Remon. Washer North face 20" Box Elder		White OF MANAGE
S61°E 92.75' Set PK & Remon. Washer North face 19" Poplar		THE CALL STATE OF THE STATE OF
N72°E 133.90' Set PK & Remon. Washer South face 23" Oak		HUSTON HEADING
THE PART AND DO VOD		STY I VENIMENT IN S

Date

The selected location is accepted by me and is generally accepted by Professional Surveyors as position of the original corner.

17623

Signed by

Surveyor's Michigan License No.