SURVEY & REMONUMENTATION

MAR 1 3 1998

1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

ı

RECEIVED FOR RECORD

97 NOV 12 PM 2: 49

S	E	\mathbf{C}	O	N	Ì

MAYFIELD TWP.

For corners in:

expressed below:

LAPEER (County)	Located in:	Corner Code #	Maliosa
Public Land Survey	T <u>.08N</u> R <u>.10E</u> T R T R T R	A-1	REGISTE LAPEER O
 Property Controlling in Section Miscellaneous Property in Sec. 	STR STR STR STR		Register of Deeds St
4. Lot No,	Recorded Plat		1 A B C D E

Meliosa De	Vaugh
REGISTER OF	TEEDS

amp & File Number

, JONATHAN M. FIELD	, in a field survey on	JUNE	19 97
do hereby certify that under requirements of P.A.	74, Michigan P.A. of	1970, the corn	er points mentioned
in lines 1 and 2 above were in conformance wi	th regulations and re	ules therefore	as required in the
current manual of survey instructions of the United	ed States Departmer	nt of the Interio	or, Bureau of Land
Management or by a decree of a Court of Law and above were in conformance with the rules of the	Michigan Roard of L	oints mentioned	I in lines 3, 4 and 5
Court of Law; established, re-established, r	nonumented, re-mor	and Surveyors Numented rec	or by a Decree of a
			T. T. CO., 100110 03

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

1 2	4 B	C D	£ F (Э Н	IJĸ	L N
2	6	5	4	3	2	j
3 4 5	7	8	9	<u>1</u> 0	···	12
6	18	17	16-	15	14	13
8	19.	20	21	22	23	24
10 11	30	29	28	27	26	25
12	- 31	32	33	34	35	36

Description of criginal monument and accessories and/or subsequent restoration:

1834 GLO; WAMPLER, D.S.; SET POST; ELM 7" S13W 80LKS., LINDEN 13" N35E 93LKS.

1977 HENDERSON-BATES; BATES, P.S.#16699; SURVEY; L.084,PG.408; SET IRON N10E 21.12' 10" BUTTERNUT, S50W 70.18' 12" OAK, S45E 47.16' 10" ASH

1978 HENDERSON-BATES; BATES, P.S.#16699; SURVEY; L.004,PG.474; FND. 1/2" ROD; SAME WITS AS 1977 SURVEY 1978 BATES, P.S.#16699; LCRC; L.003,PG.380; FND. 1/2" ROD; SAME WITS AS 1977 SURVEY ABOVE 1993 FIELD, P.S.#37276; 1993 REMON LCRC; FND. 1/2" ROD

A-13 TO A-12 2633.99' HENDERSON-BATES '77 A-13 TO M-12 2615.75' HENDERSON-BATES '77 A-13 TO L-13 2640.28' HENDERSON-BATES '77

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1997 ROWE; FIELD, PS#37276; FND. 1/2" W/ STANDARD REMON CAP

NOTE: THIS CORNER IS COMMON WITH A-13 T9N-R10E, M-13 T9N-R9E, AND M-1 T9N-R10E

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1 1/2" ROD W/ STANDARD REMON CAP

N13°E, 21.12' NAIL W/ REMON TAG IN NW FACE 10" ASH

S42°E, 47.16' NAIL W/ REMON TAG INNE FACE 8" ASH

S70°W, 70.18' NAIL W/ REMON TAG IN N. FACE 16" OAK

N64°E, 33.53' NAIL W/ REMON TAG IN NW FACE 16" WILLOW

N60°W, 36.60' NAIL W/ REMON TAG IN SW FACE 8" ASH

Signed by Date Surveyor's Michigan License No.

PROFESSIONAL SURVEYOR No 37278

M / 4

JONATHAN

M. FIELD

. IRS, JAN. 28, 1971

OFE \$ \$

REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

LIBER 0005 PAGE 0447

LACED AND CORNER +5 27 . 90 SURVEYOR

EER GROUP

9