## SURVEY & REMONUMENTATION

APR 28 1995

## COMMISSION

## REMONUMENTATION

RECEIVED FOR RECORD

94 DEC 19 AM 11: 19
LIBER NO. 05 SASE NO. 162
Heliosa Ira Vough

			RECORDATION CER		L.		≣ NO/ <u>ਦਾੜ</u> ਪੀਜ਼ਮਾਂ	_
		Filing Requireme	ent of Act 74, Mich. I	P.A. 1970			TOS / C	<del>,</del> .
Fo	or corners in				1 A P F F	GISTER DF 1 33 (22,4 Y. 14)	TUS	
	LAPEER	Located In:	Corner Code ##		LAI LU		····	
	County	MAYFIELD TOWNSHIP						
1.	Public Land Survey	T <u>8N R 10E</u> T R T R						
2.	Property Controlling							
	in Section							
3.	Miscellaneous	S T R		Register of	l Deeds Sta	emo & File	Number	
	Property in Sec.	\$ T R						-
4.	Lot No , R	ecorded Plat		A	BCDE	F G H	1 J K L 1	<u>M</u>
٦.	Private Claims			2 - 6	<del>॓</del>	-∳- <del> -</del> ∮-	├ <b>-</b> हे - ├- हे -	۲
				3	╼┼┈┼╼┼╸	┤═┼╌	<del>┞┈┞═┝╸╏</del> ┈	4
		•		4 }	·—- 8——	- 910	12-	-1
	HAROLD N. ELRIC	Hin a field survey on	AUG 10 199	94 5	╌┼╼┼╌┼╸	<del></del>	<del>                                     </del>	-
do	haraby carries that under rea	uurements of P.A. 74. Michigan P.A. 0119	)/U. the Corner points men	HIOHEO 6L.	B	-16		_
ıΠ	lines 1 and 2 above were in	conformance with regulations and ruluctions of the United States Departmen	les inerelore as required u of the interior Bureau o	of Land 7				-
* * *	ananamant or by a decree of a	a Court of t aw and/or that the corner pol	ints mentioned in illies 3, 4	4 ZIIU 3 6 1 1	20-	-2122	2324	-
ah	ove were in conformance wit	n the rules of the Michigan Board of Lar	nd Surveyors or by a Deci	regula of			<b></b>	4
Co	ourt of Law, established, r	e-established, monumented, re-monu	imented, recovered, 100	ing as	0	-28 -27	2625-	4
	pressed below:			ـــا 11			<del></del>	4
N		orners, all in the same town and ra	snge, may be recorded	12 _ 3		33 34	35-36-	4
	on this certificate.			13 🗔				۲
A.	Description of original r	monument and accessories and/or	subsequent restoration	ın:			O44 5#	
	1824 SYLVESTER	SIBLEY D.S. SET IRON ON	TRUE LINE FOR QU	JARTER SECTIO	N CORNER	R, WHITE	UAK 7"	
	N 2350	W 25 LINKS, ELM 13" S 44	½° W 34 LINKS					

N 23½° W 25 LINKS, ELM 13" S 44½° W 34 LINKS

1871 GILBERT BATES STAKE - PINE 30" N 3½° E 131 LINKS, PINE 16" N 32° E 100 LINKS

1976 ELRICH P.S. LIBER 003, PAGE 242 LAND CORNER RECORDATION CERTIFICATE

SET 1/2" IRON MID-WAY BETWEEN-STRAIGHT LINE BETWEEN SOUTHWEST CORNER OF SECTION

24 AND THE SOUTHEAST CORNER OF SECTION 24 - N 45° E 44.98 FEET CORNER POST,

S 02° W 25.78 FEET ELM CLUMP, N 75° W 77.50 FEET ELM CLUMP

1976 ELRICH P.S. LIBER 003, PAGE 811 SET 1/2" IRON (TIES MATCH 1976 LAND CORNER

RECORDATION CERTIFICATE) (SEE BACK)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ELRICH P.S. FOUND 1/2" IRON SLIGHTLY BENT 3.3 FEET SOUTH OF CENTERLINE OF OALEY ROAD.FENCE AND TREE LINE RUNNING SOUTH OF FOUND IRON.FENCE RUNNING NORTH 33.0 FEET EAST OF FOUND IRON. FOUND THREE WITNESSES FROM PREVIOUS SURVEYS THAT VERIEY THE LOCATION OF THE 1/2" IRON FOUND.

ACCEPTED THE FOUND 1/2" IRON ROD AS BEST LOCATION OF ORIGINAL POSTION OF SOUTH 1/4 CORNER OF SECTION 24, T8N-R1DE, MAYFIELD TOWNSHIP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: L-9 MONUMENT BOX PLACED OVER LOCATION OF EXISTING 1/2" IRON - RE-SET 1/2" IRON WITH REMONUMENTATION CAP IN MONUMENT BOX ACCORDING TO WITNESSES PEER GROUP APPROVED LAND CORNER

NAIL & WASHER IN 5" ELM N 10° W 35.85 FEET NAIL & WASHER IN 16" HICKORY N 40° E 93.90 FEET NAIL & WASHER IN FENCE POST N 50° E 50.46 FEET NAIL & WASHER IN ELM CLUMP S 05° W 25.35 FEET

HAY DAVIS P.S. CO. SURVEYOR DATE

PA 345 OF 1990 LAPPER COUNTY

14,407	50 B	Date 7/00, 3, 1994
Signed by		
0	18 <b>98</b> 6	187 JAN 28 187

## A. (CONTINUED)

V 35

1977 GRAVLIN P.S. UNRECORDED (TIES MATCH 1976 LAND CORNER RECORDATION CERTIFICATE)

1980 BATES P.S.LIBER 005, PAGE 937 NO OBJECT STATED (TIES MATCH 1976 LAND CORNER RECORDATION CERTIFICATE)

1984 GRAVLIN P.S. LIBER 006, PAGE 753 NO OBJECT STATED(TIES MATCH 1976 LAND CORNER RECORDATION CERTIFICATE)

1990 ELRICH P.S. LIBER 008, PAGE 692 FOUND 1/2" IRON - SOUTH 33.00 FEET 1/2" IRON, S 05° W 25.35 FEET ELM CLUMP, N 40° E 93.90 FEET 16" HICKORY

MISC D 9.00 REMLC P0075 REMONT 2.00