SURVEY & REMONUMENTATION

MAR 1 3 1998

1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

97 NOV 12 PM 2: 52

	D 7040	1	97 NOV 12 PM 2: 52
For corners in: DEERFIEI LAPEER	Located In:	Corner Code #	Melissa De Vaugh
(County)		\	REGISTER OF DEEDS
1. Public Land Survey	T <u>09N</u> R <u>10E</u> T R T R	<u>M-1</u>	LAPEER CONTINUES TO MAKE
Z. Property Commoning	T R R S T R R S T R R R R R R R R R R R	Re	egister of Deeds Stamp & File Number
Property in Sec.	s T R		ABCDEFGHIJKLM
4. Lot No Ro	ecorded Plat		2 6 5 4 3 2 1 3 4 7 8 9 10 11 12
do hereby certify that under t	edfillettlette of charter the warman	rvey on JUNE 19 97 , n P.A. of 1970, the corner points mentioned as and rules therefore as required in the epartment of the Interior, Bureau of Land	5 6 18 17 16 15 14 13 7
Management or by a decree of above were in conformance with conformance with court of Law; established	f a Court of Law and/or that the	epartment of the Interior, Bureau of Land corner points mentioned in lines 3, 4 and 5 oard of Land Surveyors or by a Decree of a land, re-monumented, recovered, found as	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
expressed below: NOTE: Not more than 4 on this certifica	l corners, all in the same to te.	own and range, may be recorded	12 31 32 33 34 35 36 13
A. Description of origina 1833 GLO; PARKE, D.	al monument and accessorie S.; SET POST; MAPLE 16 P.S.#14096; SURVEY; L.	s and/or subsequent restoration: S S26W 52LKS., BEECH 12 N63E 3 001,PG.043; 1/2" IRON; N60W 34.6	7LKS. 5' 24" MAPLE, S45E 42.1' 20" MAPLE, S45W

1971 KAY ENG.; KAY, P.S.#14096; SURVEY; L.001,PG.043; 1/2" IRON; N60W 34.6' 24" MAPLE, S45E 42.1' 20" MAPLE, S45W

1975 SMITH SURVEYING; SMITH, P.S.#21582; SURVEY; L.003,PG.432-433; FND. IRON; NO WITS GIVEN 1978 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.004,PG.676; NO OBJECT STATED; N60W 34.74' NAIL IN 24"

MAPLE, S45E 42.10' NAIL IN 20" MAPLE, SOUTH 23.00' NAIL IN 16" ASH

1987 HENDERSON-BATE; ELRICH, P.S.#18986; SURVEY; L.007,PG.718; FND. 1/2" IRON; SAME WITS AS 1978 SURVEY

1988 GRAVLIN, P.S.#23510; SURVEY; L.007,PG.885; FND. 1/2" IRON; SAME WITS AS 1978 SURVEY ABOVE

1993 FIELD, P.S.#37276; 1993 REMON LCRC FOR M-13 T10N-R10E; FND. 1/2" ROD

M-1 TO L-1 2642.52' GRAVLIN '88 & '78; SMITH '75

PEER BROUP APPROVED LAND CORNER Pa 3 13 0 F 1090 (YTKUE) MACX

lun

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 REMON-WITS CITED ABOVE 1997 ROWE; FIELD, PS#37276; FND. 1/2" W/ STANDARD REMON CAP RECOVERED ALL 1993 REMON-WITS CITED ABOVE

NOTE: THIS CORNER IS COMMON WITH M-13 T10N-R10E, A-13 T10N-R11E, AND A-1 T9N-R11E

	Description of monument for corner and accessories established to perpetuate locating the position of the corn	ier:
C.	Description of monument for corner and accessories established to perform the control of the corner and accessories established to perform the cor	نو
M-1	1/2" ROD W/ STANDARD REMON CAP	

S63°E, 77.94' NAIL W/ REMON TAG IN NE FACE CUT-OFF T.POLE

S48°E, 42.61' NAIL W/ REMON TAG IN SW FACE 26" MAPLE

S02°W, 23.87' NAIL W/ REMON TAG IN W. FACE 14" ASH

N06°W, 25.99' NAIL W/ REMON TAG IN E. FACE 10" ASH

35.49' NAIL W/ REMON TAG IN SW FACE 30" MAPLE N47°W.

Signed by Surveyor's Michigan License No. 37276

Date 11-11-97

OF MICH **JONATHAN** M. FIELD ROFESSIONAL SURVEYOR No. 37276 POFESS

REVISED MAY 14, 121. REVISED JAN., 1913 CESSING MARCH, 1993